

The City Clerk needs the following to process your appeal:

\$25 filing fee payable to the City of Saint Paul

APPLICATION FOR APPEAL

RECEIVED

Saint Paul City Clerk

FEB 1 4 2011

CITY CLERK

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

YOUR HEARING Date and Time:

Tuesday, 3-1-11

(if cash: receipt number)	Tuesday, 3-1-11
Copy of the City-issued orders or letter which	<u> </u>
are being appealed	Time_ 1:30
□ Attachments you may wish to include	Location of Hearing:
	Room 330 City Hall/Courthouse
	mailed 2-14-11
Address Being Appealed:	
Number & Street: 888 CLARK St. City:	Sr. Paul State: MN Zip: 55101
Appellant/Applicant: THOMAS E. SMITH	Email <u>Safetsmith@comeast</u> .
Phone Numbers: Business <u>651 227-9855</u> Residence <u>651</u>	
Signature: Thomas & Sinch	Date: <u>2/9/11</u>
Name of Owner (if other than Appellant):	
Address (if not Appellant's):	
Phone Numbers: Business Residence	Cell
What Is Being appealed and why?	Attachments Are Acceptable
Vacate Order/Condemnation/	•
Revocation of Fire C of O	<u> </u>
□ Summary/Vehicle Abatement	
□ Fire C of O Deficiency List	
Fine Cat O. Oak Frank XV. 1	Company of the second of the s
Code Enforcement Correction Notice	D BEDROOM WINDOWS OPEN
	TEAD OF 24".
□ Vacant Building Registration	
□ Other	
□ Other	
□ Other	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

February 2, 2011

THOMAS E. SMITH 66 9TH ST E UNIT 2506 ST PAUL MN 55101-4700

FIRE INSPECTION CORRECTION NOTICE

RE:

888 CLARK ST

Ref. #107704

Residential Class: C

Dear Property Representative:

Your building was inspected on February 1, 2011 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on March 2, 2011 at 2:00 pm.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. EXTERIOR BOTH UNITS SPLC 34.09 (3) i Provide and maintain an approved one-inch throw single cylinder deadbolt lock.-Provide deadbolts for all unit doors.
- 2. EXTERIOR SPLC 34.09 (2) 34.32 (2) Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.-Provide handrails for front exterior stairways.

- 3. EXTERIOR SPLC 34.08 (5), 34.31 (3) Repair, replace and maintain all exterior surfaces on fences, sheds, garages and other accessory structures free from holes and deterioration. Provide and maintain exterior unprotected surfaces painted or protected from the elements.-Scrape and paint house trim in a professional manner.
- 4. EXTERIOR SPLC 163.03, 163.01 (2), (3) Currently license (tabs) all vehicles on the property and return the vehicles to an operative mechanical condition or remove vehicles from the property.
- 5. EXTERIOR SPLC 34.09 (3), 34.32 (3) Provide or repair and maintain the window screens.
- 6. EXTERIOR SPLC 34.09 (3), 34.32 (3) Repair and maintain the door in good condition.-Repair or replace rear storm door.
- 7. INTERIOR BOTH UNITS SPLC 34.10 (5), 34.33 (4), 34.16 Provide and maintain interior in a clean and sanitary condition.
- 8. INTERIOR UNIT 1 SPLC 34.09 (3), 34.32 (3) Repair and maintain the window frames.-Replace window casings in front bedroom in a professional manner.
- 9. INTERIOR UNIT 1 MSFC 1011.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway.-Remove all items obstructing front entry and bedroom door in Unit 1.
- 10. INTERIOR UNIT 1 MFGC 301.3 Maintain clearance of combustibles from the space heaters in accordance with the manufacture's recommendations.
- 11. INTERIOR UNIT 2 MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-9090.-Repair damaged light fixture in living room ceiling in a professional manner.
- 12. INTERIOR UNIT 2 MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-Upon inspection, double-hung windows in Unit 2, bedroom one, measured 20 inches openable height x 25.5 inches openable width. Bedroom two measured 21.5 inches openable height x 24.5 inches openable width.
- 13. INTERIOR SPLC 34.11(5), 34.34(2), SPC 4715.0200Q Provide adequate hot water between 120 degrees F and 130 degrees F.
- 14. INTERIOR MSFC 901.6 Have fire extinguisher recharged and tagged.

For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: kelly.booker@ci.stpaul.mn.us or call me at 651-266-8985 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Kelly Booker Fire Inspector

Reference Number 107704