St. Paul Regional Water Services Vehicle Crash Summary

QTR 1- January 1st, 2025 – March 31st, 2025

Date: 2/19/25 Unit 577

• Employee was following a slow-moving vehicle traveling in the left lane. The employee attempted to pass in the right lane and but cut off a vehicle approaching in the right lane. The vehicle traveling in the right lane moved to shoulder to avoid collision and instead struck a guardrail and mailbox. According to the employee's report, the employee's speed was 10 MPH and the other vehicle was traveling at 30 MPH. **Crash was ruled preventable by the committee.**

Date: 3/24/25 Unit 604

• The truck rolled back a little bit when the truck was switching gears and struck vehicle behind it. The trailer hitch dented the license plate of the other vehicle. **Crash was ruled preventable by the committee.**