

✓ Other

APPLICATION FOR APPEAL

MAY 2 4 2012 CITY CLERK

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

1854		Telephone: (651) 266-8560
The City Clerk needs the following to pro	ocess your appeal:	
\$25 filing fee payable to the City of S (if cash: receipt number) Copy of the City-issued orders or lett are being appealed Attachments you may wish to include This appeal form completed Walk-In OR Mail-In	er which	YOUR HEARING Date and Time: Tuesday, 6-12-12 Time / 30 P.67 Location of Hearing: Room 330 City Hall/Courthouse
Address Being Appeale	ed:	
Number & Street: 1128 Maryla	nd AVE E City:	51. Paul State: MN Zip: 55106
Appellant/Applicant: Tanya Villan	MEVA	St. Paul State: MN Zip: 55106 Email TV0510Qyahoo Com
Phone Numbers: Business	Residence	cell <u>612.735.5330</u>
Signature: Iongla Villinusia		Date: 5.24.12
Name of Owner (if other than Appellant): _		
Address (if not Appellant's):		
Phone Numbers: Business	Residence	Cell
What Is Being Appeale	d and Why	? Attachments Are Acceptable
Vacate Order/Condemnation/ Revocation of Fire C of O		
□ Summary/Vehicle Abatement		
□ Fire C of O Deficiency List		
☐ Fire C of O: Only Egress Windows		
□ Code Enforcement Correction Notice _		
□ Vacant Building Registration		

windows



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951

Web: www.stpaul.gov/dsi

April 23, 2012

Federal Home Loan Mortgage Corp. 5000 PLANO PKWY CARROLLTON TX 75265

RE: RE-INSPECTION FIRE CERTIFICATE OF OCCUPANCY WITH DEFICIENCIES 1128 MARYLAND AVE E

Ref. # 111130

Dear Property Representative:

Your building was re-inspected for the Fire Certificate of Occupancy on April 2, 2012. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected immediately.

A reinspection will be made on May 29, 2012 at 1:00 pm.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

DEFICIENCY LIST

- 1. 1st Floor SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 415.0220 Repair or replace and maintain the plumbing fixture to an operational condition.-Toilet loose
- 2. 1st and 2nd Floor MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- 3. 2nd Floor North bedroom MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-Double hung window opening.

Height 17.5 in. - Width 32 in.

Glazed area 39 in. - Width 31.5 in.

4. 2nd Floor - South bedroom - MSFC1026.1 - Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-Double hung window opening.

Height 18.5 in. - Width 23 in.

Glazed area

Height 41 in - Width 19.5

- 5. Basement UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work may require a permit(s). Call DSI at (651) 266-8989.-REQUIEES PERMIT AND INSPECTION BY WARM AIR / VENT INSPECTOR. CALL 266-9006
- 6. Basement SPLC 34.12 (2), 34.35 (1) Repair and maintain all required and supplied equipment in an operative and safe condition.-Smoke detector not working.
- 7. Front door MSFC 1011.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway.
- 8. Kitchen SPLC 34.10 (7), 34.33 (6) Repair and maintain the cabinets in an approved manner.-Cabinet doors missing.
- 9. Kitchen MSFC 901.6 Provide required annual maintenance of the fire extinguishers by a qualified person and tag the fire extinguishers with the date of service.
- 10. Living room Ceiling MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.
- 11. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 12. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of the original orders.

If you have any questions, email me at mike.cassidy@ci.stpaul.mn.us or call me at 651-266-8984 between 7:30 a.m - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Mike Cassidy Fire Inspector Ref. # 111130