WORK PLAN - BREAKDOWN COST OF REHABILATION
(To be done in accordance with the Code Compliance Inspection Report) **Address:** 1187 Edgerton St

WEEK OF	TASKS	CONTRACTOR	Supplies/Materials on hand (if any)	Needed Supplies/Materials	Owner/Developer Labor	Value of Cost
	Electrical	Anthony Electric LLC				2,000.00
Jan 8th 2012	Plumbing	Century Plumbing				4,000.00
Dec 20th 2011	Heating	WD Mechanical / Mespo Heating & Cooling				5,300.00
Jan 18th 2012	Building	Van Anh Nguyen owner	windows doors bamboo for floor		✓	30,000.00
Feb 8th 2012	Clean up Done Checking with all the inspectors for reinspections				✓	

RECEIVED
NOV 22 2011
CITY CLERK

Total Project Cost: $ 41,300.00

Note: (Code Enforcement Officers estimate the cost to repair this structure is $_____ to $_____).