

# **APPLICATION FOR APPEAL**

OCT 12 2011

### Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

1854	CITY CLERK	Telephone: (651) 266-8560	
The City Clerk needs the following to process your appeal:			
\$25 filing fee payable to the City of Saint Pa (if cash: receipt number) Copy of the City-issued orders or letter whi are being appealed Attachments you may wish to include This appeal form completed  Walk-In OR   Mail-In		YOUR HEARING Date and Time:  Tuesday, 10-25-11  Time 1:30  Location of Hearing: Room 330 City Hall/Courthouse	
Address Being Appealed:  Number & Street: 991 Galter City: 50 Paul State: MU Zip:			
Appellant/Applicant: Les DasserTy Email Rent Proz a Con Cest, Net			
Appellant/Applicant: Les DargherT	Em	ail Rent Proza (a) Concept, Net	
Phone Numbers: Business 7152541540 Residence Cell 7155291512			
Signature:		Date: 10/12/11	
Name of Owner (if other than Appellant): Tony Herchler			
Address (if not Appellant's):			
Phone Numbers: Business	Residence	Cell	

## What Is Being Appealed and Why? Attachments Are Acceptable

	Vacate Order/Condemnation/	
	Revocation of Fire C of O	Item # 2 of Five Inspection 10/3/11
	Summary/Vehicle Abatement	The voom has always been a bedroom.
2	Fire C of O Deficiency List	as is There are Two egress points
	Fire C of O: Only Egress Windows	One does that her to the living your
	Code Enforcement Correction Notice	
	Vacant Building Registration	hallway.
_	Other	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

October 3, 2011

POWER HOUSE PROPERTIES LLC C/O TONY HETCHLER PO BOX 54 RIVER FALLS MN 54022-0054

#### FIRE INSPECTION CORRECTION NOTICE

RE: 991 GALTIER ST

Dear Property Representative:

Your building was inspected on October 3, 2011 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

### A re-inspection will be made on November 9, 2011 at 11 am.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

**DEFICIENCY LIST** 

1. Exterior - SPLC 34.08 (5), 34.31 (3) - Repair, replace and maintain all exterior surfaces on fences, sheds, garages and other accessory structures free from holes and deterioration. Provide and maintain exterior unprotected surfaces painted or protected from the elements.-Secure the garage and repair the chain link fence/gate to open and close as designed.

- 2. Interior- Unit 1 MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-Unable to measure windows as they are covered in plastic and exits to an enclosed porch. However, there is a large window that does not open, with two side windows that appear to have only 4 inch width. The egress window does not meet code as the window does not open, and it exits into an enclosed porch.
- 3. Interior- Unit 1 SPLC 200.02 (a) No person shall own, harbor, keep or maintain in the City and dog over three months of age without a license. Provide written documentation of current license to the Fire Inspector. To obtain a dog license, contact DSI at 651-266-8989
- 4. Interior- rear steps. MSFC 1011.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway.-Remove items from the rear steps.
- 5. Interior-Basement MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.-Provide a smoke detector in the basement that was missing. Installed on site.
- 6. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 7. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: lisa.martin@ci.stpaul.mn.us or call me at 651-266-8988 between 6:30 a.m. - 8:30 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Lisa Martin Fire Inspector