



Front entry porch in summer



NE Property Corner Survey Monument

NE Property corner survey monument close up





SE property corner monument

Debris being thrown down to dumpster



Dumping loose construction debris
into dumpster off roof





View North from SE Property Corner

KEY
BERQUIST
& SON
699-2442



View from entry porch living space-next to dumpster



View of dumpster from front entry and porch



View of dumpster from front entry

View of Dumpster from front entry porch



View of Dumpster from Front Entry Porch