

# **APPLICATION FOR APPEAL**

# Saint Paul City Council - Legislative Hearings

RECEIVED

AUG 31 2020

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

We need the following to process your appeal:	K			
\$25 filing fee (non-refundable) (payable to the City of Saint Paul) (if cash: receipt number)  Copy of the City-issued orders/letter being appealed  Attachments you may wish to include  This appeal form completed  Walk-In OR Mail-In  for abatement orders only: O Email OR O Fax	HEARING DATE & TIME (provided by Legislative Hearing Office) Tuesday, Sept. 8, 2020  Time			
Address Being Appealed:	a.m. 4 1:00 p.m. Tall to Bonnie Barlage, 470-8			
Number & Street: 1192 Earl Street City: St. Appellant/Applicant: Scott Beck	State: MN Zip: 55106  sbeck@havenbrookhomes.com			
Phone Numbers: Business Residence	Cell 612-239-3407  Date: 8/28/20			
Name of Owner (if other than Appellant): FYR SFR Bor	rower, LLC			
Mailing Address if Not Appellant's: 1611 County Rd B West, #104, Roseville, MN, 55113				
Phone Numbers: Business Residence	Cell 612-239-3407			
What Is Being Appealed and Why? Attachments Are Acceptable  Vacate Order/Condemnation/ Revocation of Fire C of O  Summary/Vehicle Abatement  Fire C of O Deficiency List/Correction  Code Enforcement Correction Notice  Vacant Building Registration  O Other (Fence Variance, Code Compliance, etc.)				

Ricardo X. Cervantes, Director

SAINT

CITY OF SAINT PAUL

375 Jackson Street. Suite 220 St Paul, Minnesota 55101-1806

Telephone: 651-266-8989 Facsimile: 651-266-9124

Web: www.stpaul.gov/dsi

August 28, 2020

SCOTT BECK HAVENBROOK HOMES 1611 COUNTY ROAD B W STE 104 **ROSEVILLE MN 55113-3907** 

## Revocation of Fire Certificate of Occupancy and Order to Vacate

RE:

1192 EARL ST

Ref. # 121633

#### Dear Property Representative:

Your building was determined to be a registered vacant building on August 28, 2020. Since certificates are for the occupancy of buildings, it has become necessary to revoke the Certificate of Occupancy.

Saint Paul Legislative Code provides that no building shall be occupied without a Certificate of Occupancy. In order to re-occupy the building, the following deficiencies (if applicable) must be corrected and a complete Certificate of Occupancy inspection will be required.

#### **DEFICIENCY LIST**

- Exterior House SPLC 34.09 (1)(2), 34.33 (1) Provide and maintain all exterior walls 1. painted or protected from the elements and maintained in a professional manner free from Chipped or peeling paint. On the back side of the house, on the second floor and the sec a corner part of the railing that was not repair and is still damaged. On the North-East corner of the house, there is a small hole near the gutter.
- 2. Interior - Basement - MMC 504.6 - Provide, repair or replace the dryer exhaust duct. mm) in diameter and installed in accordance with the mechanical code. This work may require a permit(s). Call DSI at (651) 266-8989.-A new dryer exhaust duct has been installed without a permit. The dryer duct is completely disconnected and is not properly secured. There is no permit for this installation.

  Update 8/28/2020 9:20 a.m. - no possible property and the secured of metal and shall have a minimum nominal size of four inches work may require a permit(s). Call DSI at (651) 266-8989.-A new dryer exhaust duct has been installed without a permit. The dryer duct is completely disconnected and is not properly secured. There is no permit for this installation. Interior - Living Room - MSFC 605.4 - Discontinue use of all multi-plug adapters.-There is a multi-plug adapter being used in the living room behind the television.

  An Equal Opportunity Employer

3.

- 4. Interior Living Room SPLC 34.14 (2), 34.34 (5) Provide an approved electrical service adequate to meet the buildings needs. This work may require a permit(s), call DSI at (651) 266-8989. In the living room there is a power-strip connected to another power strip and then plugged into the outlet with an adapter.
- MSBC -Section 105.1 Permits Required. Any owner or authorized agent who intends to construct, enlarge, alter, repair, move, demolish, or change the occupancy of a building or structure, or to erect, install, enlarge, alter, repair, remove, convert or replace any electrical, gas, mechanical or plumbing system, the installation of which is regulated by this code, or to cause any such work to be done, shall first make application to the building official and obtain the required permit. Work being done requires a permit.-A permit is required for the installation of the new dryer exhaust duct.
- 6. SPLC 40.06 Suspension, revocation and denial. (a) Grounds for revocation. The fire code official may, in writing, issue a notice to the owner(s) and known interested parties of the city's suspension or revocation of a fire certificate of occupancy issued under the provisions of this code, or deny an application therefor: (3) If it is found upon inspections of the fire code official that the building or occupancy is in violation of provisions of this or other applicable safety codes, ordinances, rules and regulations:-The Fire Certificate of Occupancy has been revoked due to long term non-compliance. Property is unoccupied 8/28/2020.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: leanna.shaff@ci.stpaul.mn.us or call me at 651-266-8980 between 7:30 - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Leanna Shaff Fire Safety Inspector

Ref. # 121633



# Move In/ Out Inspection

### MN68072, 1192 EARL ST ST. PAUL, MN, 55106

Inspected on August 28, 2020 12:21 PM

Report Created on August 28, 2020 12:37 PM

#### Inspector

Name: Greg Halleland

Email: ghalleland@fyrhomes.com

### Score

Total:	0	
	0	

## Laundry

	Laundry Total:	0
-		

#### **Photos**



Dryer Vent (1/6) 08/28/2020 12:22 PM



Dryer Vent (2/6) 08/28/2020 12:22 PM



Dryer Vent (3/6) 08/28/2020 12:22 PM



Dryer Vent (4/6) 08/28/2020 12:22 PM



Dryer Vent (5/6) 08/28/2020 12:22 PM



Dryer Vent (6/6) 08/28/2020 12:22 PM

## **Exterior**

Exterior Total: 0

#### **Photos**



Exterior Walls (Siding/ Stucco/ Brick) (1/3) 08/28/2020 12:26 PM



Exterior Walls (Siding/ Stucco/ Brick) (2/3) 08/28/2020 12:26 PM



Exterior Walls (Siding/ Stucco/ Brick) (3/3) 08/28/2020 12:26 PM



Patio/ Deck (1/8) 08/28/2020 12:23 PM



Patio/ Deck (2/8) 08/28/2020 12:23 PM



Patio/ Deck (3/8) 08/28/2020 12:23 PM



Patio/ Deck (4/8) 08/28/2020 12:23 PM



Patio/ Deck (5/8) 08/28/2020 12:25 PM



Patio/ Deck (6/8) 08/28/2020 12:25 PM



Patio/ Deck (7/8) 08/28/2020 12:25 PM



Patio/ Deck (8/8) 08/28/2020 12:25 PM