

WORK PLAN - BREAKDOWN COST OF REHABILITATION

(To be done in accordance with the Code Compliance Inspection Report)

Address: 694 Sherborne NE

WEEK OF	TASKS	CONTRACTOR	Supplies/Materials on hand (if any)	Needed Supplies/Materials	Owner/Developer Labor	Value of Cost
		OWNER				
2 20 Minu	Fire rate door			2" X 350	400	700
	Self closing door			6 X 62	300	312
2 Exterior	Storm door		on hand		200	
Attic	Sheet rocks			10 X 10	500	100
Front door	Weather seal			1	60	50
	Raft Vent		on hand		400	
	Smoke Detectors			3	60	120
2nd Floor	Kitchen Vignal		on hand		100	
2nd Floor	Window			2 X 220	200	440
	MISC				6000	
					2160	1782

Total Project Cost: \$ 9942⁰⁰

Note: (Code Enforcement Officers estimate the cost to repair this structure is \$ _____ to \$ _____).