

Date: November 15, 2010
File #: 10 - 922778
Folder Name: 627 OHIO ST
PIN: 072822240146

HP District:
Property Name:
Survey Info:



South and west sides



East and north sides



East side, posting



South and east sides, posting



Front posting



Rear posting

Date: November 15, 2010
File #: 10 - 922778
Folder Name: 627 OHIO ST
PIN: 072822240146

HP District:
Property Name:
Survey Info:



Shed

Date: July 13, 2011
File #: 10 - 922778
Folder Name: 627 OHIO ST
PIN: 072822240146

HP District:
Property Name:
Survey Info:



North and west face of the west side dormer, missing flashing, water damage siding

Date: July 13, 2011
File #: 10 - 922778
Folder Name: 627 OHIO ST
PIN: 072822240146

HP District:
Property Name:
Survey Info:



Unapproved exterior electrical wiring

Date: July 13, 2011
File #: 10 - 922778
Folder Name: 627 OHIO ST
PIN: 072822240146

HP District:
Property Name:
Survey Info:



Water damaged ceiling, peeling paint, possibly mold

Date: July 13, 2011
File #: 10 - 922778
Folder Name: 627 OHIO ST
PIN: 072822240146

HP District:
Property Name:
Survey Info:



South and west face of the west side dormer, missing flashing, water damaged siding