

**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020




Missing wall tiles

**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020




**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020





**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020




Bedroom light spliced w. extension cord

**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020



**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020



Front door deadbolt replaced w. handset



Date: May 23, 2013



**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020



Kitchen wall coverings sticky floor tiles were used which are broken.



**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020



**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020





**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020



Carpeting in the rear entryway

**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020



Broken closet door in rear entryway




**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020




Basement stairs with no handrail and garbage on stairs

Date: May 23, 2013






**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020



Storage next to water heater


**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020



Cat litter and feces in basement



Date: May 23, 2013






**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020






Date: May 23, 2013





**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020



Unapproved use of extension cords



**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020



Date: May 23, 2013  
File #: 07 - 033241  
Folder Name: 1009 SEMINARY AVE  
PIN: 262923330020



Outdated fire extinguishers



**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020



**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020






**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020



**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020



Garage is packed full. Approved parking space issue could be resolved if cleaned out and made available for current tenants.




**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020



Garage

**Date:** May 23, 2013  
**File #:** 07 - 033241  
**Folder Name:** 1009 SEMINARY AVE  
**PIN:** 262923330020



Garage