

APPLICATION FOR APPEAL

Saint Paul City Council - Legislative Hearings


RECEIVED
JAN 18 2018

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

Revised 8/11/2014

We need the following to process your appeal: CITY CLEDIA	
\$25 filing fee (non-refundable) (payable to the City of Saint Paul)	
(if cash: receipt number)	(provided by Legislative Hearing Office)
Copy of the City-issued orders/letter being appealed	Tuesday, Jan 23
Attachments you may wish to include	Time 1:30 p.m.
This appeal form completed	Location of Hearing:
t∕ Walk-In OR □ Mail-In	Room 330 City Hall/Courthouse
for abatement orders only: Email OR Fax	
Address Being Appealed:	
Number & Street: 2314 411LLSIDE City: STPAUL State: MX zip: 55108	
Appellant/Applicant: GLOKKA METER GLOKKA. GTAL CO	
Phone Numbers: Business 612 414 7534 Residence Cell 612414 7534	
Signature: Date: 70n 18 2018	
Name of Owner (if other than Appellant):	
Mailing Address if Not Appellant's:	
Phone Numbers: Business Residence	Cell
What Is Being Appealed and Why? Attachments Are Acceptable	
Vacate Order/Condemnation/	11000000000000000000000000000000000000
Revocation of Fire C of O	
□ Summary/Vehicle Abatement	
If Fire C of O Deficiency List/Correction # 6 on kin to keen the door to	
- Code Enforcement Correction Notice retein the old floor & feel of the house	
□ Vacant Building Registration	
□ Other (Fence Variance, Code Compliance, etc.)	

Mieczyslaw



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

January 11, 2018

MIECZYSLAW GLOWKA 2330 HILLSIDE AVE ST PAUL MN 55108

FIRE INSPECTION CORRECTION NOTICE

RE:

2314 HILLSIDE AVE

Ref. #11442

Residential Class: B

Dear Property Representative:

Your building was inspected on January 10, 2018 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on February 9, 2018 at 2:45 PM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. Interior Basement Gasline MFGC 406.5.2 Immediately repair or replace the leaking fuel equipment piping. This work requires a permit(s). Call DSI at (651) 266-8989.- Faint smell of gas behind new dryer installation in basement. Cat crates stored in room behind dryer. No windows to open and ventilate.
- 2. Interior Basement Appliances MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.-

- 3. Interior Hard-wired Smoke Detectors SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.
 Smoke detector was provided at the start of inspection, but many of the smoke detectors are out of date (2006) and had not been replaced prior to inspection. Battery operated smoke detectors are in place in sleeping rooms at time of inspection. Hardwired smoke detectors are required to work at final inspection. Additional SDA enclosed.
- 4. Interior Old Dryer in Basement SPLC 34.12 (2), SPLC 34.36 (1) Repair and maintain all required and supplied equipment in an operative and safe condition to properly and safely perform their intended function in accordance with the provisions of the applicable code.
 Remove the old dryer from basement if not in use.
- 5. Interior See Comments NEC 440.13 For cord-connected equipment such as: room air conditioners, household refrigerators and freezers, drinking water coolers, and beverage dispensers, a separable connector or an attachment plug and receptacle shall be permitted to serve as the disconnecting means. The appliance must plug directly into a permanent outlet.
 Chest freezer and refrigerator plugged into extension cords to outlet.
- 6. Interior Units 1 & 2 Entry Doors MSFC 703.1 Provide, repair or replace the fire rated door and assembly. The minimum rating must be 20 minutes.- In common corridor.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: laura.huseby@ci.stpaul.mn.us or call me at 651-266-8998 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Laura Huseby Fire Inspector

Reference Number 11442