WORK PLAN - BREAKDOWN COST OF REHABILATION
(To be done in accordance with the Code Compliance Inspection Report) **Address:** 595 Park St

WEEK OF	TASKS	CONTRACTOR	Supplies/Materials on hand (if any)	Needed Supplies/Materials	Owner/Developer Labor	Value of Cost
4-14	Mechanical	PMR				
4-17	Drywall	A-1				
4-17	Kitchen Cabinet	A-1				
4-24	doors/trims	A-1				
5-1	painting	A-1				
5-1	baseboards	A-1				
5-8	Plubming fixture	Barr Web				
5-8	lighting	K-Pow				
5-15	Mechanical finish	PMR				
5-22	Flooring	A-1				

Total Project Cost: **$**_____

Note: (Code Enforcement Officers estimate the cost to repair this structure is $_____ to $_____).