

WORK PLAN - BREAKDOWN COST OF REHABILITATION

(To be done in accordance with the Code Compliance Inspection Report) Address: _____

WEEK OF	TASKS	CONTRACTOR	Supplies/Materials on hand (if any)	Needed Supplies/Materials	Owner/Developer Labor	Value of Cost
4-24-23	bathroom	AychoeumTe	tiles		Paid	1,500
4-30-23	kitchen	OudamTumTe	full cabinet		Paid	2,500
			stove		Paid	1050
			refrigerator		Paid	540
4-24-23	framing door and window lock		Framing have all			
	Heat	Turn on Heat				
4-24-23	door					
	garage	in AychoeumTe	Trim			
	house		paint		Paid	300
	in house	AychoeumTe	paint		Paid	30
	(install flooring than hand cabinet thank		floor Vinyl			

Heat will install the stove by Heating.

Total Project Cost: \$ _____

Note: (Code Enforcement Officers estimate the cost to repair this structure is \$ _____ to \$ _____).