

INSPECTION REQUEST

Address this form to: MAILING LIST - FORM4 (District Chief, and Yourself).

| | | |
|--|--|---|
| Date: | 02/05/2019 | |
| Property Address: | 535 Forest St. | |
| Owner Name: | Vanna Yean/Malika Keo | |
| Owner Phone: | 651-699-6190 | |
| Owner Address: | 7597 Sherwood Rd Woodbury MN 55125 | |
| Occupant Name: | n/a (vacant) | |
| Occupant Phone: | n/a (vacant) | |
| Check the following corrections: | | |
| <input type="checkbox"/> Address Nos. <input type="checkbox"/> Exit Doors <input checked="" type="checkbox"/> Housekeeping <input type="checkbox"/> Keybox <input type="checkbox"/> Sprinkler System | <input type="checkbox"/> Hydrants <input type="checkbox"/> Hazardous Material <input type="checkbox"/> Fire Alarm System <input type="checkbox"/> Smoke Detector <input type="checkbox"/> Standpipe | <input type="checkbox"/> Fire Lane <input type="checkbox"/> Electrical <input type="checkbox"/> Fire Extinguishers <input checked="" type="checkbox"/> Heating Plant <input type="checkbox"/> Welding <input type="checkbox"/> OTHER _____ |
| Check the type of property: | <input checked="" type="checkbox"/> Single family or duplex <input type="checkbox"/> Multi family (3 Units or more) <input type="checkbox"/> Commercial | |
| Describe: | While assisting a medic unit, Ladder #7 noted that this is a vacant building being used by squatters. There is trash everywhere and apparently the squatters have been burning materials and using the oven for warmth. The Comm Center was contacted and put in a call for police to respond. | |
| Name: Brian Kroeger | Rank: District Chief | Company: C3 |
| Response: | | |
| Name: | Date: | Phone: |