

**Date:** March 03, 2011  
**File #:** 11 - 105671  
**Folder Name:** 777 UNIVERSITY AVE W  
**PIN:** 352923130223

**HP District:**  
**Property Name:**  
**Survey Info:**



**North side**



**East and south sides**



**East and south sides**



**South side, posting**



**South side, posting**



**Front posting**

Date: March 03, 2011  
File #: 11 - 105671  
Folder Name: 777 UNIVERSITY AVE W  
PIN: 352923130223

HP District:  
Property Name:  
Survey Info:



Front posting



Front posting



Garage



Warehouse

**Date:** July 6, 2011  
**File #:** 11 - 105671  
**Folder Name:** 777 UNIVERSITY AVE W  
**PIN:** 352923130223

**HP District:**  
**Property Name:**  
**Survey Info:**



**Water damaged window and wall**



**Water damaged ceiling and wall, mold**



**Water damaged walls and ceiling, mold**



**Unapproved electrical wiring**



**Unapproved and open electrical wiring**



**Water damaged walls and floor covering, mold**

Date: July 6, 2011  
File #: 11 - 105671  
Folder Name: 777 UNIVERSITY AVE W  
PIN: 352923130223

HP District:  
Property Name:  
Survey Info:



Water damaged, partially collapsed ceiling, mold



Water damaged ceiling, mold



Water damaged, partially collapsed ceiling



Open wall



Sagging ceiling panels



Water damaged ceiling panels

Date: July 6, 2011  
File #: 11 - 105671  
Folder Name: 777 UNIVERSITY AVE W  
PIN: 352923130223

HP District:  
Property Name:  
Survey Info:



Water damaged and partially collapsed ceiling



Ceiling debris on floor



Water damaged walls, mold



Water damaged wall and ceiling, mold



Water damaged wall and wood work, mold



Water damaged wall

**Date:** July 6, 2011  
**File #:** 11 - 105671  
**Folder Name:** 777 UNIVERSITY AVE W  
**PIN:** 352923130223

**HP District:**  
**Property Name:**  
**Survey Info:**



**Water damaged ceiling**



**Water damaged ceiling, mold**



**Basement steps - no hand rail**



**Unapproved, leaking plumbing, apartment**



**Apartment kitchen floor**



**Deteriorated, open roof**

Date: July 6, 2011  
File #: 11 - 105671  
Folder Name: 777 UNIVERSITY AVE W  
PIN: 352923130223

HP District:  
Property Name:  
Survey Info:



Water heater installation



Water damaged ceiling and wall, apartment



Ceiling debris on apartment floor



Water damaged, partially collapsed apartment ceiling



Water damaged ceiling, apartment



Sagging flat roof

**Date:** July 6, 2011  
**File #:** 11 - 105671  
**Folder Name:** 777 UNIVERSITY AVE W  
**PIN:** 352923130223

**HP District:**  
**Property Name:**  
**Survey Info:**



**Water heater installation**



Date: September 02, 2011  
File #: 11 - 105671  
Folder Name: 777 UNIVERSITY AVE W  
PIN: 352923130222


HP District:  
Property Name:  
Survey Info:



OTA posting on front door

Date: September 02, 2011  
File #: 11 - 105671  
Folder Name: 777 UNIVERSITY AVE W  
PIN: 352923130222


HP District:  
Property Name:  
Survey Info:



OTA posting on front door

Date: September 02, 2011  
File #: 11 - 105671  
Folder Name: 777 UNIVERSITY AVE W  
PIN: 352923130222

HP District:  
Property Name:  
Survey Info:



OTA posting on front door