

Date: April 05, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157




- Dryer vent NOT
installed under permit
& not meeting code

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157




- Fence - Dangerous

Date: April 05, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157




- open Ground

Date: April 05, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



- Ceilings
- electric fixture not working - no bulb - no globe cover

Date: April 05, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



missing detector

Date: April 05, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157




- carpets #1

Date: April 05, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



- missing Celobe cover
#1

Date: April 05, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



water heaters

Date: April 05, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157




water heaters

Date: April 05, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



water heater

Date: April 05, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



Water Heater

Date: April 05, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



- Basement walls
- mechanical ducts