



APPLICATION FOR APPEAL

Saint Paul City Clerk
310 City Hall, 15 W. Kellogg Blvd.
Saint Paul, Minnesota 55102
Telephone: (651) 266-8560

RECEIVED
MAY 07 2012

The City Clerk needs the following to process your appeal: **CITY CLERK**

- \$25 filing fee payable to the City of Saint Paul (if cash: receipt number _____)
- Copy of the City-issued orders or letter which are being appealed
- Attachments you may wish to include
- This appeal form completed
- Walk-In OR Mail-In

YOUR HEARING Date and Time:
 Tuesday, 5-15-12
 Time 1:30 P.M.
Location of Hearing:
 Room 330 City Hall/Courthouse

Address Being Appealed:

Number & Street: 1672 Wellesley Ave City: St. Paul State: mn Zip: 55105

Appellant/Applicant: Carey DeNicola Email cdenicola@mainstreamboutique.com

Phone Numbers: Business (952) 891-1378 Residence _____ Cell (952) 818-0039

Signature: [Signature] Date: 4/27/12

Name of Owner (if other than Appellant): _____

Address (if not Appellant's): _____

Phone Numbers: Business _____ Residence _____ Cell _____

What Is Being Appealed and Why? *Attachments Are Acceptable*

- Vacate Order/Condemnation/Revocation of Fire C of O *See Attached
- Summary/Vehicle Abatement _____
- Fire C of O Deficiency List _____
- Fire C of O: Only Egress Windows _____
- Code Enforcement Correction Notice _____
- Vacant Building Registration _____
- Other _____

DEFICIENCY LIST

1. Double hung windows - MSFC1026.1 - Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.-
Second floor - southwest
21.5 h x 26 w Glazed 7.5 sq ft
Second floor north
17.5 h x 29 w Glazed 8.3 sq ft
First floor
17.5 h x 29 w Glazed 8.3 sq ft



CITY OF SAINT PAUL
Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220
Saint Paul, Minnesota 55101-1806

Telephone: 651-266-8989
Facsimile: 651-266-8951
Web: www.stpaul.gov/dsi

January 30, 2012

COREY DENICOLA
1622 WELLESLEY AVE
ST PAUL MN 55105

RE: RE-INSPECTION FIRE CERTIFICATE OF OCCUPANCY WITH DEFICIENCIES
1622 WELLESLEY AVE

Dear Property Representative:

Your building was re-inspected for the Fire Certificate of Occupancy on January 30, 2012. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected immediately.

A reinspection will be made on February 29, 2012 at 1:00 PM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

DEFICIENCY LIST

1. Double hung windows - MSFC1026.1 - Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.-
Second floor - southwest
21.5 h x 26 w Glazed 7.5 sq ft
Second floor north
17.5 h x 29 w Glazed 8.3 sq ft
First floor
17.5 h x 29 w Glazed 8.3 sq ft
2. Exterior - SPLC 34.09 (3), 34.32 (3) - Repair and maintain the window glass.

3. Exterior - SPLC 34.09 (1) b,c, 34.32 (1) b,c - Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.-Repair damaged siding on west side of house.
4. Front door - SPLC 34.09 (3), 34.32 (3) - Repair and maintain the door in good condition.- Provide an approved door handle. Replace or repair in an approved manner.
5. Garage - MSFC 605.6 - Provide electrical cover plates to all outlets, switches and junction boxes where missing.
6. SPLC 34.11 (6), 34.34 (3) - Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
7. SPLC 39.02(c) - Complete and sign the provided smoke detector affidavit and return it to this office.
8. SPLC 34.09 (3), 34.32 (3) - Repair and maintain the window lock.-second floor windows
9. MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
10. UMC 504.6 - Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work requires a permit(s). Call DSI at (651) 266-8989.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: <http://www.stpaul.gov/cofo>

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of the original orders.

If you have any questions, email me at rick.gavin@ci.stpaul.mn.us or call me at 651-266-8994 between 7:30 a.m - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Rick Gavin
Fire Inspector

COREY DENICOLA
1622 WELLESLEY AVE
ST PAUL MN 55105

RE: RE-INSPECTION FIRE CERTIFICATE OF OCCUPANCY WITH
DEFICIENCIES
1622 WELLESLEY AVE

Dear Property Representative:

Your building was re-inspected for the Fire Certificate of Occupancy on January 30, 2012. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected immediately.

**A reinspection will be made on February 29, 2012
at 1:00 PM.**

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

DEFICIENCY LIST

1. Double hung windows - MSFC1026.1 - Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.-
Second floor - southwest
21.5 h x 26 w Glazed 7.5 sq ft
Second floor north
17.5 h x 29 w Glazed 8.3 sq ft

First floor

17.5 h x 29 w Glazed 8.3 sq ft

2. Exterior - SPLC 34.09 (3), 34.32 (3) - Repair and maintain the window glass.
3. Exterior - SPLC 34.09 (1) b,c, 34.32 (1) b,c - Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.-Repair damaged siding on west side of house.
4. Front door - SPLC 34.09 (3), 34.32 (3) - Repair and maintain the door in good condition.-Provide an approved door handle. Replace or repair in an approved manner.
5. Garage - MSFC 605.6 - Provide electrical cover plates to all outlets, switches and junction boxes where missing.
6. SPLC 34.11 (6), 34.34 (3) - Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
7. SPLC 39.02(c) - Complete and sign the provided smoke detector affidavit and return it to this office.
8. SPLC 34.09 (3), 34.32 (3) - Repair and maintain the window lock.-second floor windows
9. MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
10. UMC 504.6 - Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in

diameter. This work requires a permit(s). Call DSI at (651) 266-8989.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: <http://www.stpaul.gov/cofo>

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of the original orders.

If you have any questions, email me at rick.gavin@ci.stpaul.mn.us or call me at 651-266-8994 between 7:30 a.m - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Rick Gavin
Fire Inspector