



10/09/2014

10/09/2014

C
POST'S
Sitting on
Slab only
No Figs.





Slab
is
Sinking
Bottom of
Stairway.

10/09/2014



Post
Sitting on
Concrete Slab
at Stgs.

10/09/2014



No
Connections





POSTS
Sitting on
Top of
Deckers only
No support
Under for
floor joist
or to
Cure steps.
Holds up
Roof load.





No support
for post

10/09/2014



Improper
Construction

10/09/2014



Spliced
OUT of post.
Very Bad
Connection
&
Unsafe.






Splice
Top of
Post.
+ Improper
Connections.









Improper
Connections







10/09/2014



10/09/2014

Doubt if
Just
for Proper
Construction.



Improper
Connectors.

Improper
Connections































10/09/2014



10/09/2014



10/09/2014



10/09/2014













