

APPLICATION FOR APPEAL

RECEIVED

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

Saint Paul City Clerk

1854	Telephone: (651) 266-8560
The City Clerk needs the following to process your app	
\$25 filing fee payable to the City of Saint Paul (if cash: receipt number <u>Cash</u>) Copy of the City-issued orders or letter which are being appealed Attachments you may wish to include CMNAThis appeal form completed Walk-In OR Mail-In	YOUR HEARING Date and Time: Tuesday, 7-17-12 Time 1:30 P. M. Location of Hearing: Room 330 City Hall/Courthouse
Address Being Appealed:	
Number & Street: 287-PAGE St. C	City: Haw State: MN Zip:
Appellant/Applicant: Bill Berniev	Email bbernier@usfamily
	e Cell 651-276-974/
Signature: SM Slme	Date: 7-3-12
Name of Owner (if other than Appellant):	
Address (if not Appellant's): 846-314 Auss	s So. St-Paul, MN 55075
Phone Numbers: Business Residence	e Cell
What Is Being Appealed and W	the removal, repair + rebuilding
Vacate Order/Condemnation/	part of the retaing wall belonging
Summary/Vehicle Abatement/	adita for the orlabenist of the new
Fire C of O Deficiency List	with he hemitit at all to me propert
Fire C of O: Only Egress Windows This wall wa	as apparently built by these proper
Code Enforcement Correction Notice Comments	they would be able to build sheds
Vacant Building Registration was to the very	back inch of their lots, These she
Other - one of which to gon	e - whe also built without regar
to the proper rear, also, and therefor	set back requirements Revised 4/22/2011 needs to be moved.
, , , , , , , , , , , , , , , , , , , ,	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

June 26, 2012

BILL BERNIER 846 3RD AVE S SOUTH ST PAUL MN 55075-3007

FIRE INSPECTION CORRECTION NOTICE

RE:

287 PAGE ST E

Ref. #113474

Residential Class: B

Dear Property Representative:

Your building was inspected on June 26, 2012 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A reinspection will be made on July 26, 2012 at 2:15 pm.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. Exterior Back Yard MSFC 304.1 Remove excessive combustible storage and/or vegetation from exterior property areas.-Remove all brush and vegetation from back yard.
- 2. Exterior Fire Pit MSFC 307.1 Fire Prevention has been receiving complaints regarding fires conducted on your property. All fires on the ground must be a minimum of 25 feet from structures or contained in a grill or outdoor fireplace. Wind speeds must be under 10 mph, constantly attended, a means of extinguishment must be provided. Only natural firewood can be burned (no construction materials, brush or waste materials), and fire shall be extinguished if the smoke is deemed a nuisance. A citation will be issued for non-compliance.-Remove or replace with an approved contained fireplace or grill.

- 3. Exterior North Back Yard SPLC 34.08 (2) Provide and maintain the property grade to slope away from the building to minimize the accumulation of water near the building. This work may require a permit(s). Call DSI at (651) 266-9090.-Repair grading and drainage along area where retaining wall fell over and left the ground exposed.
- 4. Exterior North Retaining Wall SPLC 34.08 (5), 34.31 (3) Repair, replace and maintain all exterior surfaces on fences, sheds, garages and other accessory structures free from holes and deterioration. Provide and maintain exterior unprotected surfaces painted or protected from the elements.-Retaining wall separating and falling over. Repair or replace north cement retaining wall.
- 5. Unit 1 Northwest Bedroom MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.-Missing cover plate on north bedroom wall.
- 6. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 7. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: sean.westenhofer@ci.stpaul.mn.us or call me at 651-266-8982 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Sean Westenhofer Fire Inspector Ref. #113474