

Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:
before: repair unfinished sheetrock



Date Completed:
before: repair unfinished sheetrock



Date Completed:
before: repair/pressure wash stucco



Date Completed:
before: repair/pressure wash stucco

Account #: 9900158385


Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:
before: repair/pressure wash stucco



Date Completed:
before: repair/pressure wash stucco



Date Completed:
before: repair/replace window sash holder 1st flo



Date Completed:
before: repair/replace sheetrock

Account #: 9900158385


Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909




Date Completed:
before: repair/replace window panes



Date Completed:
before: repair/replace window panes



Date Completed:
before: repair/replace window sash holder 1st floor



Date Completed:
before: replace

Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:
before: replace basement toilet



Date Completed:
before: replace broken sash cord upstairs bedroom



Date Completed:
before: replace broken sash cord upstairs bedroom



Date Completed:
before: replace broken sash cords 1st floor living

Account #: 9900158385


Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909




Date Completed:
before: replace broken sash cords 1st floor living



Date Completed:
before: replace broken sash cords 1st floor living



Date Completed:
before: replace broken sash cords 1st floor living



Date Completed:
before: replace broken sash cords 1st floor living

Account #: 9900158385

Order #: 1195745


Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:

before: replace broken sash cords upstairs




Date Completed:

before: replace broken sash cords upstairs



Date Completed:

before: replace broken sash cords upstairs



Date Completed:

before: replace cast iron

Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:

before: replace corroded cast iron




Date Completed:

before: replace corroded piping



Date Completed:

before: replace fixture



Date Completed:


before: replace fixture

Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:
before: replace fixtures



Date Completed:
before: replace fixtures



Date Completed:
before: replace front entry door



Date Completed:
before: replace front entry door

Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:
before: replace gas piping



Date Completed:
before: replace gas piping



Date Completed:
before: replace gas shut off valve




Date Completed:
before: replace heating register

Account #: 9900158385


Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:
before: replace heating register



Date Completed:
before: replace heating register



Date Completed:
before: replace heating register



Date Completed:
before: replace heating register

Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:
before: replace heating register



Date Completed:
before: replace heating register



Date Completed:
before: replace heating vent




Date Completed:
before: replace kitchen sink

Account #: 9900158385

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1195745

Case #: 703271-9209909




Date Completed:

before: replace laundry tub stand pipe



Date Completed:

before: replace light fixture



Date Completed:

before: replace light fixture



Date Completed:


before: replace light fixtures

Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909




Date Completed:
before: replace outlets



Date Completed:
before: replace outlets



Date Completed:
before: replace outlets



Date Completed:
before: replace outlets

Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909




Date Completed:
before: replace pipe



Date Completed:
before: replace piping



Date Completed:
before: replace piping



Date Completed:
before: replace piping

Account #: 9900158385


Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:
before: replace piping



Date Completed:
before: replace piping



Date Completed:
before: replace piping



Date Completed:
before: replace piping

Account #: 9900158385

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1195745


Case #: 703271-9209909



Date Completed:
before: replace piping



Date Completed:
before: replace piping



Date Completed:
before: replace piping




Date Completed:
before: replace piping

Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:
before: replace piping



Date Completed:
before: replace piping



Date Completed:
before: replace piping



Date Completed:
before: replace piping

Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106


Case #: 703271-9209909



Date Completed:
before: replace piping



Date Completed:
before: replace piping



Date Completed:
before: replace piping




Date Completed:
before: replace piping

Account #: 9900158385

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1195745


Case #: 703271-9209909



Date Completed:
before: replace piping



Date Completed:
before: replace piping



Date Completed:
before: replace piping




Date Completed:
before: replace piping

Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:
before: replace piping



Date Completed:
before: replace piping



Date Completed:
before: replace piping



Date Completed:
before: replace piping

Account #: 9900158385

Order #: 1195745


Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:

before: replace replace laundry tub stand pipe




Date Completed:

before: replace sheetrock in entry ways between dw



Date Completed:

before: replace shut off valve



Date Completed:


before: replace sink

Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:
before: replace stand pipe



Date Completed:
before: replace storm window



Date Completed:
before: replace storm window



Date Completed:
before: replace storm window

Account #: 9900158385

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1195745

Case #: 703271-9209909




Date Completed:
before: replace toilet



Date Completed:
before: replace tub



Date Completed:
before: replace tub



Date Completed:
before: replace tub

Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:
before: replace tub



Date Completed:
before: replace tub



Date Completed:
before: replace unfinish sheetrock



Date Completed:
before: replace vent

Account #: 9900158385


Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1195745

Case #: 703271-9209909



Date Completed:
before: replace vent piping



Date Completed:
before: replace vent piping



Date Completed:
before: replace window pane upstairs



Date Completed:
before: replace window screens