

Drain relief pipe for water heater from
977 Reaney Ave - Unit 2. The pipe is not properly
supported.

Date: December 01, 2015
File #: 12 - 204266
Folder Name: 975 REANEY AVE
PIN: 282922340120



Drain relief pipe for water heater from 977 Reaney-
Unit 2. The pipe is not properly supported

Date: December 01, 2015
File #: 12 - 204266
Folder Name: 975 REANEY AVE
PIN: 282922340120



Date: December 01, 2015
File #: 12 - 204266
Folder Name: 975 REANEY AVE
PIN: 282922340120

Furnace Room for 977 Reaney - Unit 2. The ceiling is not repair and maintained. The caulking around the exhaust pipe is not an approved form of sealing the openings.



Date: December 01, 2015
File #: 12 - 204266
Folder Name: 975 REANEY AVE
PIN: 282922340120



Date: December 01, 2015
File #: 12 - 204266
Folder Name: 975 REANEY AVE
PIN: 282922340120

The tenant for 975 Reaney Ave - Unit 2 has lots of shoes obstructing the front entry door. The tenant; "in good faith" stated they will pick up all the shoes.



Date: December 01, 2015
File #: 12 - 204266
Folder Name: 975 REANEY AVE
PIN: 282922340120

975 Reaney - Unit 2 - Dead mice on glue
traps discovered underneath the kitchen
sink cabinet.



Date: December 01, 2015
File #: 12 - 204266
Folder Name: 975 REANEY AVE
PIN: 282922340120

975 Reaney Ave- Unit 2 - Dead mice on glue
traps discovered underneath the
kitchen sink cabinet.



975 Reaney - Unit 2 - Large opening for pipes
underneath the kitchen sink cabinet. The opening
is large enough for insects and rodents to travel
through.

Date: December 01, 2015
File #: 12 - 204266
Folder Name: 975 REANEY AVE
PIN: 282922340120



Date: December 01, 2015
File #: 12 - 204266
Folder Name: 975 REANEY AVE
PIN: 282922340120

975 Reaney Ave - Unit 2 - Dead mice on
glue trap discovered underneath the
kitchen sink cabinet.



Date: December 01, 2015
File #: 12 - 204266
Folder Name: 975 REANEY AVE
PIN: 282922340120

975 Reaney Ave - Hallway - The Stairway
has steps that have black rubber grips
and many are missing. The 5th step in the
picture has a piece that is has a piece cracked off.



975 Revery Ave. - Unit 2

RP stated they installed
a new toilet.

The tenant states that
a new toilet was not

installed.

There is an toilet
sitting in the hallway.

RP Permal has

been at the



975 Reaney - Unit 2
Toilet sitting in the
2nd floor hallway.

