

□ Other

APPLICATION FOR APPEAL

RECEIVED
FEB 1 3 2012
CITY CLERK

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

The City Clerk needs the following to process your appeal:	
\$25 filing fee payable to the City of Saint Paul (if cash: receipt number)	YOUR HEARING Date and Time:
Copy of the City-issued orders or letter which	7-1
are being appealed	Tuesday, 7Ebruary 21, 2012
☐ Attachments you may wish to include ☐ This appeal form completed	Time
	Location of Hearing:
₩alk-In OR □ Mail-In	Room 330 City Hall/Courthouse
Address Being Appealed:	
Number & Street: 967 Wakefeld City: 51, Paul State: Muzip:	
Appellant/Applicant: Jason Oberhawer Email obez4240yqhow.com (oberhamer)	
Phone Numbers: Business 612-721-888 Residence	Cell 612-382-0965
Signature: Date: 2/13/12	
Name of Owner (if other than Appellant): DRS Brows, LLC	
Address (if not Appellant's): 506 N Lexingen May	
Phone Numbers: Business 613-721-888 Residence Cell	
What Is Being Appealed and Why? Attachments Are Acceptable	
Vacate Order/Condemnation/ Revocation of Fire C of O Size of Will	lows just under acceptable
Summary/Vehicle Abatement Olening	
□ Fire C of O Deficiency List	
Fire C of O: Only Egress Windows	
Code Enforcement Correction Notice	
□ Vacant Building Registration	
□ Vacant Building Registration	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

January 13, 2012

SCOT SORUM C/O CITIES HOME RENTALS 1845 STINSON PKWY, STE 212 MINNEAPOLIS MN 55418-4897

FIRE INSPECTION CORRECTION NOTICE

RE:

967 WAKEFIELD AVE

Ref. #114624

Residential Class: B

Dear Property Representative:

Your building was inspected on January 12, 2012 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on February 14, 2012 at 1:30pm.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

1. Egress Windows - MSFC1026.1 - Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651) - 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.

Main Floor

Northwest Bedroom (Double-hung)

21h x 25.5w - Openable 48h x 24w - Glazed

Northeast Bedroom (Double-hung)

18.5h x 25.5w - Openable 48h x 24w - Glazed

Upper Floor

North and South Bedroom (Double-hung)

20h x 20ww - Openable 40h x 20w - Glazed

- 2. Garage MSFC 605.1 Repair or replace damaged electrical fixtures. This work requires a permit(s). Call DSI at (651) 266-9090.-The light fixture above the garage service door is not installed correctly. Contact a licensed electrical contractor to install the garage light fixture in accordance with all electrical codes. This work must be done under permit.
- 3. Main Floor Fireplace NFPA 211,9-2 Have the chimneys, fireplaces, and vents inspected for soundness, freedom from deposits, and correct clearances. Cleaning, maintenance, and repairs shall be done if indicated by the inspection.
- 4. Main Floor and Upper Floor SPLC 34.09 (3), 34.32 (3) Repair and maintain the door in good condition.-Repair/replace the doors that are not closing and latching in the main floor northwest bedroom, the rear porch storm door, the upper floor north bedroom, and the upper floor stairway.
- 5. Main Floor and Upper Floor SPLC 34.09 (3), 34.32 (3) Repair and maintain the window lock.-Repair/replace the window locks on the main floor bathroom window and the upper floor south bedroom window.
- 6. Upper Floor North and South Bedrooms and Garage MSFC 605.5 Discontinue use of extension cords and multi-plug adapters used in lieu of permanent wiring.
- 7. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo.

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: wayne.spiering@ci.stpaul.mn.us or call me at 651-266-8993 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Wayne Spiering Fire Inspector

Reference Number 114624