


Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



missing lock

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



Unit 2
electric panel label.

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



Unit 2

Frayed wires


Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



Unit 2

- incorrect fuses
- frayed wires

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



Unit 2

Fuse box

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157




- ceiling tiles falling
- light fixture hanging
- missing globe cover

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



missing screens

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157




- The floor vent does not cover the large hole in the floor.

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157




- interior wall
- missing screen

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



- Floor install
- not a professional state of maintenance.

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



- walls - ceiling covered
in spider webs


Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



- Rear fence

neighbor's fence

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157




Rear Garbage

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157




- Furnace - conodact

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



Water heaters - corroded

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



dryer vent does
not meet code &
not connected.