

Date: October 13, 2011
File #: 11 - 288018
Folder Name: 110 DOUGLAS ST
PIN: 012823410142

HP District:
Property Name:
Survey Info:



North and west sides



Front posting



North side eaves



West side eaves



North side unfinished and unapproved siding installation



North side unfinished and unapproved siding installation

Date: October 13, 2011
File #: 11 - 288018
Folder Name: 110 DOUGLAS ST
PIN: 012823410142

HP District:
Property Name:
Survey Info:



Unfinished south side light fixture



South side unapproved siding installation



Rot damaged rear steps



East side unfinished window installation



Eave of the east side flat roof



North side missing siding, abandoned window

Date: October 13, 2011
File #: 11 - 288018
Folder Name: 110 DOUGLAS ST
PIN: 012823410142

HP District:
Property Name:
Survey Info:



North side eaves



North side eave, unfinished window installation



East side



West and south sides



West side