



City of Saint Paul
Smoke Testing Inspection Report

DRAFT

Date Printed: 9/4/2014

Record No: 211

Project No: 127489

General Location Information

Address: 1442 Berkley Ave

General Location: House

X Coordinate: 557,562

Daily Work

Schedule: 42

Note:

Y Coordinate: 151,877

Inspection Information

Date/Time: 7/22/2014

By: PJK

Weather Conditions: Sunny

Ground Conditions: Moderate

Blower Location MH ID: 108204

Manhole Notes:

Upstream MH ID: 108205

Downstream MH ID: 108202

Defect Found? Yes

Defect Number: 1

Defect Notes: Downspout connection under bricks

Smoke Density: Heavy

Sector: Private

Smoke Source: Downspout Connection

Smoke Source Location: Other-(addnote)

Smoke Source Notes:

Smoke Source Location Notes: NE corner of house

Surface: Grass/Sod

Additional

Surface Notes:

Notes:

DNC

Runoff Area: 2

Additional Testing:



Photo 1 : Photo1.jpg



Photo 2 : Photo2.jpg