

Work plan - Breakdown cost of rehabilitation
to be done in accordance with the Code Compliance inspection report

Address: 694 Sherburne Ave

Week Of	Task	Contactore	Supplies/Materials On hand	Needed Supplies/Materials	Owner developer labor	Value of Cost
11/1/2022	20 Minn fire rate door self closind devices	Owner		2 doors 6 self closing	400 300	1500 1000
11/10/2022	weather seal Exterior door	Owner		3 pieces	80	200
11/14/2022	Install floor to bath Kitchen	owner		2 Vynal		440
11/18/2022	Repair walls, Ceiling floor	Owner		Compound Paint		2000
11/25/2022	Paint exterior	Owner		Paint		800
11/30/2022	Wall Remove	Owner		Attic 2x8 10		1000.00
12/5/2022	Air Seal attic	Owner		seal		300
12/6/2022	Smoke Dectectors	Owner		3		180
12/10/2022	Water Proof enclosure Shower area	Owner		4 pieces		100.00
12/12/2022	Bath Exhaust Venting	Owner				300
12/15/2022	Siding fascia	Owner	On hand			200
12/20/2022	One hour fire Separation	Owner				500.00
12/30/2022	Proper draining	Owner	On hand dirt	20 bags Mulch		200
1/3/2022	House roof vent to code	Owner	On hand		Misc	500 3000
						10720