

Date: January 05, 2012
File #: 12 - 001221
Folder Name: 880 ROSE AVE E
PIN: 282922220036

HP District:
Property Name:
Survey Info:

photo #1



2/1
to clean up

Date: January 05, 2012
File #: 12 - 001221
Folder Name: 880 ROSE AVE E
PIN: 282922220036

HP District:
Property Name:
Survey Info:

photo #2



2/1
to clean up -

Date: January 05, 2012
File #: 12 - 001221
Folder Name: 880 ROSE AVE E
PIN: 282922220036

HP District:
Property Name:
Survey Info:

photo #3



2/1
to clean-up

Date: January 05, 2012
File #: 12 - 001221
Folder Name: 880 ROSE AVE E
PIN: 282922220036

HP District:
Property Name:
Survey Info:

photo
#4



2/1
deadline to
clean up

gone a/p 1-17-12
per owner

Date: January 05, 2012
File #: 12 - 001221
Folder Name: 880 ROSE AVE E
PIN: 282922220036

HP District:
Property Name:
Survey Info:

photo
5



another
bonding ally
slat

2/15
deadline

Date: January 05, 2012
File #: 12 - 001221
Folder Name: 880 ROSE AVE E
PIN: 282922220036

HP District:
Property Name:
Survey Info:

photo #6



2/15
deadline
to clean up

Date: January 05, 2012
File #: 12 - 001221
Folder Name: 880 ROSE AVE E
PIN: 282922220036

HP District:
Property Name:
Survey Info:

photo # 7



↑
Railing appears
to be sagging

Need building permit
and
improper extension
storage

2/15/12
to clean up


Date: January 05, 2012
File #: 12 - 001221
Folder Name: 880 ROSE AVE E
PIN: 282922220036

HP District:
Property Name:
Survey Info:

Photo # 8



The back of
building alley
benches painted
blue



Date: January 05, 2012
File #: 12 - 001221
Folder Name: 880 ROSE AVE E
PIN: 282922220036

HP District:
Property Name:
Survey Info:

photo #9



says he's
using screws
junk to support
structure -

pile of extra lumber
to be used on
garage

7/1/12
pile gone -