

| SPRWS Claim | Date of Injury | Division | Job Title | Injury Description | Body Part | Days Lost | Days Restrict | Recordable |
|-------------|----------------|--------------|----------------------------|---|-------------------------------------|-----------|---------------|------------|
| 22-032 | 10/6/2022 | Distribution | WATER SYSTEM WORKER II | Backfilling hole on street, something flew into his right eye. | Body Part | 0 | 0 | no |
| 22-033 | 10/10/2022 | Engineering | WATER METER TECHNICIAN | Lifting box weighing approximately 30-35 lbs, felt pain in back | back | 0 | 7 | Yes |
| 22-034 | 11/11/2022 | Distribution | WATER UTILITY TECHNICIAN I | EMPLOYEE JUMPED INSIDE A WORK VAN TO RETRIEVE A TOOL. THE VAN DOOR WAS NOT FULLY OPEN, AS A RESULT THE EMPLOYEE HIT HIS HEAD ON THE BOTTOM OF THE DOOR AND FELT PAIN IN HIS NECK ON THE LEFT SIDE. SYMPTOMS AGGRAVATED WHEN SLEEPING ON LEFT SIDE THAT NIGHT. | neck | 0 | 0 | No |
| 22-035 | 12/12/2022 | Production | WATER UTILITY WORKER I | Cleaning at Vadnais plant, safety harness chaffed inner thighs & lower left buttock. Lyme was present in area being cleaned. | inner thighs and left lower buttock | 0 | 0 | No |
| 22-036 | 12/12/2022 | Production | WATER UTILITY WORKER I | Cleaning at Vadnais plant, safety harness chaffed inner thighs & lower left buttock. Lyme was present in area being cleaned. | both inner thighs | 0 | 0 | No |