


96 Manitoba



1st floor




1st floor



New furnace



1st floor




2nd floor clutter removed




2nd floor wall repaired




2nd floor clutter



Smoke and Carbon detector
and floor working




2nd floor Smoke det.



2nd floor Carbon detector ✓

ok here!



outside clutter all removed



outside clutter all removed





1st floor Broken windows



clutter removed by stairs



1st floor broken windows



Window & door



First floor Broken




1st floor broken walls



1st floor broken window




1st floor broken windows





1st floor smoke detector removed




1st floor smoke detector removed





Smoke detector removed



1st floor busted walls



1st floor broken bathroom



1st floor clutter before

1st floor clutter be forse



New furnace



New furnace





Second floor wall repaired



Basement clutter all removed,