

Photos Taken 1/16/13

549 Nevada Ave E Exhibit 8

Upstairs door with 2x4
screwed in



SE Bedroom Ceiling







↵

upstairs door




South Bedroom Ceiling



Ceiling in NE Bedroom and light fixture



SE Bedroom Ceiling



Dining Room Ceiling



Living Room Window




Living Room Windows



Upstairs Bedroom Windows



Upstairs window



~~Living Room~~
Dining Room
Ceiling



Bedroom Ceiling



Bedroom
Ceiling




Kitchen Ceilings after trespasser
Removed and stole kitchen cabinets



2 - Living Room Windows




SE
Bedroom
Ceiling



Living Room Ceiling Corrected

Outside window sash/vinyl clad
and frame



East living room window -
Glass broken by trespasser.
When he removed and stole window air conditioner



Outside Window Sash - Vinyl CLAD
and frame



outside window sashes - vinyl clad
and frames



sliding glass door frame



outside window sash/vinyl-clad
and frame



Top of sliding glass door frame