

**WORK PLAN - BREAKDOWN COST OF REHABILITATION**

(To be done in accordance with the Code Compliance Inspection Report)

Address: 318 Edmund Ave

WEEK OF	TASKS	CONTRACTOR	Supplies/Materials on hand (if any)	Needed Supplies/Materials	Owner/Developer Labor	Value of Cost
12-14-22	insulation	OUDam Tun	supplies on hand			
12-14-22	sheet Rock	Tea				
1-16-23	doors		bedroom door			
	kitchen		table sink			
	bath Room		Toilet sing., shower pan + Light			
	Light (finit)					
	siding Repair					
1-15-23	flood		cabinet			
1-15-23	garage door					Cost \$2,000 <sup>±</sup> estimate

Total Project Cost: \$ 2,000<sup>±</sup>

Note: (Code Enforcement Officers estimate the cost to repair this structure is \$ \_\_\_\_\_ to \$ 2,000<sup>±</sup>).

RECEIVED  
DEC 13 2022  
CITY CLERK