

□ Other

APPLICATION FOR APPEAL

RECEIVED
AUG 2 5 2011
CITY CLERK

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

The City Clerk needs the following to process your appeal:	
\$25 filing fee payable to the City of Saint Paul (if cash: receipt number) Copy of the City-issued orders or letter which are being appealed Attachments you may wish to include This appeal form completed Walk-In OR Mail-In	YOUR HEARING Date and Time: Tuesday, Oth U Time / ', 3 O Location of Hearing: Room 330 City Hall/Courthouse
Address Being Appealed:	
Number & Street: 758 6th St. E City: St. Paul State: MN Zip: 55106	
Appellant/Applicant: Resurrection of Christ, Inc. Email TUSMnche MSN. com	
Phone Numbers: Business 763 574 - 1001 Residence 763 574 - 7560 Cell	
Signature: Ks. John Magranum Name of Owner (if other than Appellant): S/A	Date: Aug. 23, 2011
Address (if not Appellant's):	
Phone Numbers: Business Residence	Cell
What Is Being Appealed and Why Vacate Order/Condemnation/ Revocation of Fire C of O Summary/Vehicle Abatement Fire C of O Deficiency List	? Attachments Are Acceptable
□ Fire C of O: Only Egress Windows	
Code Enforcement Correction Notice	
▼ Vacant Building Registration	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-9124

 Web:
 www.stpaul.gov/dsi

Code Compliance Report

August 16, 2011

Orthodox Church of The Resurrection of Christ, Inc 1201 Hathaway Ln Ne Minneapolis MN 55432-5720

Re: File#: 758 6th St E 10 903993 VB2

Dear Property Owner:

The following is the Code Compliance report you requested on March 24, 2011.

Please be advised that this report is accurate and correct as of the date August 16, 2011. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from August 16, 2011. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected:

BUILDING Inspector: Jim Seeger Phone: 651-266-9046

- Insure basement cellar floor is even, is cleanable, and all holes are filled.
- Install plinth blocks as needed under posts in basement & ensure adequate footing for load imposed.
- Tuck Point interior/exterior of foundation as necessary.
- Dry out basement and eliminate source of moisture.
- Remove mold, mildew and moldy or water damaged materials.
- Permanently secure top and bottom of support posts in an approved manner.
- Install handrails (34 inches 38 inches above each nosing) and guardrails (36 inch minimum) at all stairways, and return hand rail ends into a newel post or wall per attachment.
- Provide complete storms and screens, in good repair for all door and window openings.
- Weather seal exterior doors, threshold and weather-stripping.
- Repair walls, ceiling and floors throughout, as necessary.
- Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present.
- Air-seal and insulate attic/access door.

Re: 758 6th St E August 16, 2011

Page 2

BUILDING Inspector: Jim Seeger Phone: 651-266-9046

- Install Smoke Detectors/Carbon Monoxide Detectors per MN Co Conservation Code and the MN Dept. of Labor and Industry.
- Provide major clean-up of premises.
- Repair siding, soffit, fascia, trim, etc. as necessary.
- Provide proper drainage around house to direct water away from foundation of house.
- Install downspouts and a complete gutter system.
- Install rain leaders to direct drainage away from foundation.
- Provide durable, dustless parking surface as specified in the zoning code.
- Remove trees which are against foundation of home and garage.
- Install front handrail at street to code.
- Replace front porch floor and foundation and jack up porch.
- Remove garage from rear yard.
- Replace siding and roofing to code and insure weather barrier installed to code and flash.
- Replace east side decayed floor joist or sister joist, decayed end.
- East side of house sagging at about 12 feet in from south end; needs to be jacked up and supported.
- Install egress window in rear west side bedroom.
- Install vapor barrier in crawl space.
- A building permit is required to correct the above deficiencies.

ELECTRICAL Inspector: Peggy Schlichte Phone: 651-266-9039

- Ground the electrical service to the water service with a copper conductor within 5 feet of the entrance point of the water service
- Bond around water meter with a copper wire sized for the electrical service per Article 250 of the NEC
- Provide a complete circuit directory at service panel indicating location and use of all circuits
- verify/install a separate 20 ampere laundry circuit and a separate 20 ampere kitchen appliance circuit
- Verify that fuse/circuit breaker amperage matches wire size
- Close openings in service panel/junction box with knock out seals, breaker blanks and/or junction boxes
- Properly strap cables and conduits in basement
- Ground bathroom light in basement/first bathroom/second bathroom and disconnect receptacle on fixture
- Repair or Replace all broken, missing or loose light fixtures, switches and outlets, covers and plates
- Check all outlets for proper polarity and verify ground on 3-prong outlets
- Remove any 3-wire ungrounded outlets and replace with 2-wire or ground 3-wire to code
- Install hard-wired, battery backup smoke detector per bulletin 80-1 and other smoke detectors as required by the IRC. Also, Install carbon monoxide detector(s) within 10 feet of all bedrooms

Re: 758 6th St E August 16, 2011

Page 3

ELECTRICAL Inspector: Peggy Schlichte Phone: 651-266-9039

- Remove and or/ re-wire all illegal, improper or hazardous wiring in basement/garage
- Throughout building, install outlets and light fixtures as specified in Bulletin 80-1.
- Note: No access to walls do to storage throughout house.
- All added receptacles must be grounded, tamper-resistant and be on an Arc-Fault Circuit Interrupter-protected circuit.
- Any open walls or walls that are opened as part of this project must be wired to the standards of the current NEC.
- All buildings on the property must meet the St. Paul Property Maintenance Code (Bulletin 80-1).
- All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

PLUMBING Inspector: Denny Watters Phone: 651-266-9051

- Basement Water Heater gas venting incorrect (IFGC 503)
- Basement Water Heater not fired or in service (MPC 2180)
- Basement Water Meter remove meter from pit (MPC 88.08) Could not find water meter repair as necessary.
- Basement Water Piping boiler fill water line requires backflow assembly or device (MPC 2100)
- Basement Gas Piping dryer gas shutoff; connector or piping incorrect (IFGC 402.1) strap to wall.
- Basement Gas Piping range gas shut off; connector or piping incorrect (IFGC 411 1.3.3) strap to wall
- Basement Gas Piping run dryer vent to code (IFGC 613.1 IMC 604.1)
- Basement Soil and Waste Piping no front sewer clean out (MPC 1000)
- Basement Laundry Tub provide a vacuum breaker for the spout (MPC 2000 B)
- Basement Laundry Tub unvented (MPC 0200 E)
- Basement Laundry Tub waste incorrect (MPC 2300)
- First Floor Toilet New double fee.
- First Floor Gas Piping range gas shut off; connector or piping incorrect (IFGC 411 1.3.3)
- First Floor Lavatory waste incorrect (MPC 2300) new double fee
- First Floor Sink waste incorrect (MPC 2300) new double fee.
- First Floor Tub and Shower unvented (MPC 0200. E) new double fee
- Exterior Lawn Hydrants Requires backflow assembly or device (MPC 2000)
- Obtain plumbing permits prior to commencement of work.

HEATING Inspector: Maureen Hanson Phone: 651-266-9043

- Install approved lever handle manual gas shutoff valve on boiler and remove unapproved valve.
- Clean and Orsat test boiler burner. Check all controls for proper operation. Provide documentation from a licensed contractor that the heating unit is safe.

Re: 758 6th St E August 16, 2011

Page 4

HEATING Inspector: Maureen Hanson Phone: 651-266-9043

- Replace boiler flue venting to code.
- Connect boiler and water heater venting into chimney liner.
- Vent clothes dryer to code.
- Provide adequate combustion air and support duct to code.
- Provide support for gas lines to code.
- Plug, cap and/or remove all disconnected gas lines.
- Provide a window in the bathrooms with an aggregate glazing area of not less than 3 square feet, one-half of which must be openable or provide exhaust system vented to outside. A mechanical ventilation permit is required if an exhaust system is installed.
- Provide heat in every habitable room and bathrooms.
- Pipe boiler pressure relief valve discharge to within eighteen inches of the floor.
- Install back flow preventer on city water fill line to hot water heating system and pipe vent as required.
- Repair or replace fin tube radiation and covers as needed.
- Remove space heater and cap and seal all openings.
- Gas and hydronic mechanical permits are required for the above work.

ZONING

- 1. This property is in a(n) RT1 zoning district.
- 2. This property was inspected as a Single Family Dwelling.

Notes:

- See attachment for permit requirements and appeals procedure.
- This property is in a designated Heritage Preservation District and all exterior work is subject to HPC guidelines and review before permits are issued. See attached explanation of design review process.
- There was considerable storage/clutter within property at the time of the inspection. Property is to meet appropriate Codes when complete.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected in accordance with the Minimum Housing Standards of the St. Paul Legislative Code (Chapter 34) and all required permits must receive final approval within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

Re: 758 6th St E August 16, 2011 Page 5

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

If you have any questions regarding this inspection report, please contact Jim Seeger between 7:30 - 9:00 AM at 651-266-9046 or leave a voice mail message.

Sincerely,

James L. Seeger
Code Compliance Officer
Department of Safety and Inspections
City of Saint Paul
375 Jackson Street, Suite 220
Saint Paul MN 55101

Phone: 651-266-9046

Email: james.seeger@ci.stpaul.mn.us

JLS:ml Attachments