

Date: September 26, 2012
File #: 12 - 109775
Folder Name: 210 GRAND AVE
PIN: 012823410015

HP District:
Property Name:
Survey Info:



East side



Front posting



South side



North wall



Front door threshold



Damaged window opening

Date: September 26, 2012
File #: 12 - 109775
Folder Name: 210 GRAND AVE
PIN: 012823410015

HP District:
Property Name:
Survey Info:



Damaged window opening



Damaged window opening



Opening in the north wall



Shed



West side



South side eave