

APPLICATION FOR APPEAL

Saint Paul City Council - Legislative Hearings

RECEIVED

MAY 06 2015

CITY CLERK

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

We need	the	follo	wing	to	process	vour	appeal:
					7		* *

- \$25 filing fee payable to the City of Saint Paul (if cash: receipt number Check 1379
- X Copy of the City-issued orders/letter being appealed
- Attachments you may wish to include
- OX This appeal form completed
- Walk-In OR Mail-In

for abatement orders only:

| Email OR □ Fax

Number & Street: 376 Maria Are City: St. Paul

HEARING DATE & TIME	
(provided by Legislative H	[earing Office)
Tuesday, May 12, 7	015
Time 130 PM	,
Location of Hearing:	
Room 330 City Hall/Court	house

Address Being Appealed:

Number & Street: 376 Warlace Ne City: 51.16ml State: MN Zip: 55706
Appellant/Applicant: MFCA Email Will Anderson 320 Comcasi
Phone Numbers: Business Residence Cell 65/248-2058
Signature:
Name of Owner (if other than Appellant): Will Anderson
Mailing Address if Not Appellant's: 6230 1074 St. N #430 OakLe 55729
Phone Numbers: Business Residence Cell 651. 248.2058
What Is Being Appealed and Why? Attachments Are Acceptable
Vacate Order/Condemnation/ Revocation of Fire C of O
□ Summary/Vehicle Abatement
Fire C of O Deficiency List Heat Test Beicks + Mortan - "Starting to deteriorate"
Code Enforcement Correction Notice
□ Vacant Building Registration
Other
Revised 5/31/2013



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: <u>www.stpaul.gov/dsi</u>

May 4, 2015

MFCA ATT WILL ANDERSON 6230 10TH ST N STE 430 OAKDALE MN 55128

FIRE INSPECTION CORRECTION NOTICE

RE:

374 MARIA AVE

Ref. #11701

Dear Property Representative:

Your building was inspected on April 29, 2015 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A reinspection will be made on May 28, 2015 at 1:00pm.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. #1 Unit door Ext. Door SPLC 34.09 (3), 34.33 (3) Repair and maintain the door in good condition.-The unit door was missing the strike plate.
- 2. #2 Bathroom SPLC 34.09 (3), 34.32 (3) Repair and maintain the door latch.-
- 3. #2 Bathroom SPLC 34.10 (7), 34.34 (6) Repair and maintain the ceiling in an approved manner.-

- 4. #2 Bathroom SPLC 34.14 (3), MPC 4715.200.T Provide and maintain a window or approved ventilation system in all bathrooms.
- 5. #2 Bathroom SPLC 34.11, MSBC 2902.1, SPLC 34.17, MSPC 415.0220 Repair or replace and maintain all parts of the plumbing system to an operational condition.-The toilet was loose to the floor.
- 6. #2 Kitchen SPLC 34.10 (7), 34.33 (6) Repair and maintain the cabinets in an approved manner.-
- 7. #3 Bathroom SPLC 34.10 (7), 34.34 (6) Repair and maintain the ceiling and walls in an approved manner.-
- 8. #3 Bathroom SPLC 34.14 (3), MPC 4715.200.T Provide and maintain a window or approved ventilation system in all bathrooms.-The vent fan was covered with plastic.
- 9. #3 Bathroom SPLC 34.11, MSBC 2902.1, SPLC 34.17, MSPC 415.0220 Repair or replace and maintain all parts of the plumbing system to an operational condition.-The toilet was running.
- 10. #3 Kitchen SPLC 34.10 (7), 34.34 (6) Repair and maintain the ceiling in an approved manner.-
- 11. #3 Porch SPLC 34.09 (3), 34.32 (3) Repair and maintain the window sash.-The sash was rotting out on one of the windows.
- 12. #3 Unit door MSFC 703 Provide, repair or replace the fire rated door and assembly.- Repair and maintain the door latch.
- 13. Exterior Bricks and mortar SPLC 34.09 (1) b,c, 34.33 (1) b, c Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.-There are several areas where the bricks are starting to deteriorate, and there are also several areas where the mortar is deteriorating.
- 14. First floor South west corner SPLC 34.09 (3), 34.32 (3) Repair and maintain the window glass.-
- 15. Interior Residential unit #4, and Commercial space including basement SPLC 34.19 Provide access to the inspector to all areas of the building.-
- 16. Residential Rear stairs MSFC 1028.3 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway.-Remove storage from back stairwell.

- 17. Residential Rear stairs SPLC 34.10 (7), 34.34 (6) Repair and maintain the walls and ceiling in an approved manner.
- 18. Residential Rear stairs SPLC 34.10 (7), 34.33 (6) Repair or replace and maintain the woodwork in an approved manner.-There was missing trim around the windows in the rear exitway.
- 19. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 20. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310-City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: george.niemeyer@ci.stpaul.mn.us or call me at 651-266-8991 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

George Niemeyer Fire Inspector

Reference Number 11701

Sile 310