



Work Order Update

Client: FANNIE MAE	Loan: 1696323483
	Loan Type: REO
	Mortgagor: Given, None
	Address: 717 FRY STREET SAINT PAUL, MN 55104
Sent Date: 01/17/2014	Work Order#: 139953974

TO : ADAM CHUMLEY
FROM : Grass Cut Department EXT: 2399
TITLE : Grass Cut Specialist
WORK ORDERED: SNOW REMOVAL

Property inspected on 01/14/14 and found to be vacant.

Property stands alone.

The Snow Removal was completed.
Length: 0 ft.
Depth: 5 inches
A city sidewalk is not present.
Description:
None

Miscellaneous Work Completed:
Snow Removal Description: None
Depth of snow: 5
Is there a city sidewalk?: NO
Length of driveway: 0

Damages:
Previously Reported Damages Include:
Mold Damage
No new damages visible from exterior.

Invoice to Follow.

If receiving this update by fax please access our website
at www.safeguardproperties.com



Client: FANNIE MAE
Loan: 1696323483
Loan Type: REO

Mortgagor: Given, None
Address: 717 FRY STREET
SAINT PAUL, MN 55104



Description: Condition Front Of House
Order Number: 139953974
CompletedDate: 1/14/2014



Description: Condition General Property
Condition
Order Number: 139953974
CompletedDate: 1/14/2014



Description: Before Snow Removal
Order Number: 139953974
CompletedDate: 1/14/2014



Description: Before Path to House Snow
Removal
Order Number: 139953974
CompletedDate: 1/14/2014



Description: Before Path to House Snow
Removal
Order Number: 139953974
CompletedDate: 1/14/2014



Description: Condition General Property
Condition
Order Number: 139953974
CompletedDate: 1/14/2014



Description: Before Snow Removal
Order Number: 139953974
CompletedDate: 1/14/2014



Description: Before Snow Removal
Order Number: 139953974
CompletedDate: 1/14/2014



Description: During Salt Other
Order Number: 139953974
CompletedDate: 1/14/2014



Description: During Salt Path to House
Order Number: 139953974
CompletedDate: 1/14/2014



Description: During Salt Other
Order Number: 139953974
CompletedDate: 1/14/2014



Description: After Path to House Snow
Removal
Order Number: 139953974
CompletedDate: 1/14/2014



Description: After Snow Removal
Order Number: 139953974
CompletedDate: 1/14/2014



Description: After Snow Removal
Order Number: 139953974
CompletedDate: 1/14/2014