

APPLICATION FOR APPEAL

DEC 0 6 2012 CITY CLERK

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

		49350 10
The City Clerk needs	the following to	process your appeal:

- \$25 filing fee payable to the City of Saint Paul (if cash: receipt number 351903)
- Copy of the City-issued orders or letter which are being appealed
- Attachments you may wish to include
- ☑ This appeal form completed
- ⊌ Walk-In OR □ Mail-In

YOUR HEARING Date and Time:		
Tuesday, Dec. 18, 2012		
Time		
Location of Hearing:		
Room 330 City Hall/Courthouse		

Address Being Appealed:

	,	
Appellant/Applicant: Dan Cisler	Email dancis () mninter.net	
Phone Numbers: Business	Residence 952541-9725 Cell 763 458-4303	
Signature: Dan Cisler	Date: 12/6/12	
Name of Owner (if other than Appellant):	Dan Cislen	
Address (if not Appellant's): 2230	Ridge Drive # 12, St. Louis Park, MN 55	
Phone Numbers: Business	Residence 952 541-972 Cell 763 458-4303	
What Is Being Appealed and Why? Attachments Are Acceptable		
Vacate Order/Condemnation/	items 4, 5 and 8	
Revocation of Fire C of O Summary/Vehicle Abatement	(lems 1,) and o	
▼ Fire C of O Deficiency List		
☐ Fire C of O: Only Egress Windows	,	
Code Enforcement Correction Notice		
□ Vacant Building Registration		
□ Other		

Number & Street: 1299 54. Albans St. N. City: 54 Paul State: MN Zip: 55117



CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

November 21, 2012

DANIEL M CISLER 2230 RIDGE DRIVE UNIT 12 ST LOUIS PARK MN 55416

FIRE INSPECTION CORRECTION NOTICE

RE:

1299 ST ALBANS ST N

Ref. #105954

Residential Class: C

Dear Property Representative:

Your building was inspected on November 16, 2012 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on January 7, 2013 at 1:00pm.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

1. Basement - Dryer Vent - UMC 504.6 - Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter.-Remove the unapproved duct tape holding the joints together on the dryer exhaust duct and replace with approved material. Screws are not permitted in the dryer exhaust duct.

- 2. Basement and Lower Unit Plumbing SPLC 34.11 (4), 34.34 (1), MPC 4715.0900 MPC 4715.0220S Provide and maintain an approved waste trap.-Contact a licensed plumbing contractor to remove the unapproved S-trap on the lower unit kitchen sink and basement utility sink and replace in accordance with the plumbing code. This work must be done under permit.
- 3. Basement and Upper Unit Stairway SPLC 34.10 (3) 34.33(2) Provide an approved guardrail and handrail. Intermediate balustrades must not be more than 4 inches apart. Intermediate rails must be provided if the height of the platform is more than 30 inches. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.-Install the required guardrail on the basement stairway and install the required handrail on the west entry stairway to upper unit.
- Exterior Driveway SPLC 34.08 (7) All parking spaces shall be paved with asphalt, concrete, or durable dustless surfacing. Before any existing spaces may be paved, site plan approval must be obtained as specified in the St. Paul Zoning Code. Contact DSI Zoning at 651-266-9090.-The driveway consists of class 5 gravel. This is not an approved parking surface. Provide an approved parking surface for the driveway.
- Garage Electrical Wiring MSFC 605.1 Remove unapproved exposed wiring and install in accordance with the electrical code. This work may require a permit(s). Call DSI at (651) 266-9090.-There is electrical wiring in the garage that is not installed correctly. Contact a licensed electrical contractor to remove the incorrectly installed electrical wiring and install in accordance with the electrical code. This work must be done under permit.
 - 6. Lower Unit Basement and East Bedroom Door SPLC 34.09 (3) i Provide and maintain an approved one-inch throw single cylinder deadbolt lock. Install the required dead-bolt lock on the door between the lower unit and the basement and the door in the lower unit east bedroom that leads to the interior stairway.
 - 7. Lower Unit Bathroom SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 415.0220 Repair or replace and maintain the plumbing fixture to an operational condition.-Secure the loose toilet.
 - Lower Unit East Bedroom MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651) 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.

Note: The egress window opens into an enclosed porch and not directly to the outdoors.

9. Lower Unit - Kitchen - MSFC 901.6 - Have fire extinguisher recharged and tagged.-The fire extinguisher was last serviced in 1994. Remove, replace, or service the fire extinguisher.

- 10. Lower Unit Kitchen SPLC 34.12 (2), 34.35 (1) Repair and maintain all required and supplied equipment in an operative and safe condition.-Replace the missing knobs for the gas range.
- 11. Lower Unit and Upper Unit MSFC 1011.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway.-Remove or reposition the cable cords in the lower unit living room and remove the material stored on the east interior stairway that creates an exit obstruction.
- 12. Upper Unit Living Room and Bedroom MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.-Remove and discontinue use of the extension cords and electrical adapters in the upper floor living room and bedroom. The window A/C unit must be plugged directly into a permanently grounded outlet and not into a power-strip.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo.

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

days of the date of this order.

R m 376

If you have any questions, email me at: wayne.spiering@ci.stpaul.mn.us or call me at 651-266-8993 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Wayne Spiering Fire Inspector

Reference Number 105954