

Date: July 7, 2011
File #: 08 - 155990
Folder Name: 846 SMITH AVE S
PIN: 072822330185

HP District:
Property Name:
Survey Info:



Closer view of missing shingles and damaged eave



damaged, open eave



Rot damaged, open eave



Missing shingles and chimney flashing (closer view)



Missing shingles and chimney flashing



Rear entry

Date: July 7, 2011
File #: 08 - 155990
Folder Name: 846 SMITH AVE S
PIN: 072822330185

HP District:
Property Name:
Survey Info:



West side



Damaged, open eave and roof



Damaged, open eave



Unfinished electrical upgrade



Gas meter locked off



30-amp service drop (closer view)

Date: July 7, 2011
File #: 08 - 155990
Folder Name: 846 SMITH AVE S
PIN: 072822330185


HP District:
Property Name:
Survey Info:




30-amp electrical service drop



Eave and roof damage



Eave damaged by tree (closer view)



Eave damaged by tree



Eave damaged by tree and rot



North and west sides

Date: July 7, 2011
File #: 08 - 155990
Folder Name: 846 SMITH AVE S
PIN: 072822330185

HP District:
Property Name:
Survey Info:



Missing shingles, damaged, open eave