


Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



- screen
- sidewalks, steps

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



sidewalk - trip hazard

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



- Front Steps

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157




Front entry walk

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157




- side of home
- siding

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



— Carbage

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



Screening

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



Rear storm door

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



missing Colopla

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



missing smoke
detectors

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



Kitchen - Unit 1

vacant

Date: June 23, 2011
File #: 11 - 010737
Folder Name: 869 ALBEMARLE ST
PIN: 252923410157



Window frames/Locks