

Date: May 09, 2011
File #: 11 - 139117
Folder Name: 77 CONGRESS ST E
PIN: 082822220059

HP District:
Property Name:
Survey Info:



Shed



Front posting



East and north sides, posting



East side, posting



South and west sides

Date: March 6, 2012
File #: 11 - 139117
Folder Name: 77 CONGRESS ST E
PIN: 082822220059

HP District:
Property Name:
Survey Info:



North and west sides



Dry toilet trap, staining in front of toilet



Open wiring, no fixture box



Mold



Open wiring, no fixture box



Broken window

Date: March 6, 2012
File #: 11 - 139117
Folder Name: 77 CONGRESS ST E
PIN: 082822220059

HP District:
Property Name:
Survey Info:



Broken windows



Mold



Mold on ceiling



South and east sides, posting



Shed



Electric meter yellow tagged off

Date: March 6, 2012
File #: 11 - 139117
Folder Name: 77 CONGRESS ST E
PIN: 082822220059

HP District:
Property Name:
Survey Info:



Damaged components of the central air conditioner



Damaged components of the central air conditioner