Q2 2023 Employee Injury Summary

| SPRWS# | Date of Injury | Date Reported | Division | Job Title | Injury Description | Body Part |
|--------|----------------|---------------|----------------|----------------------------|---|-------------------------------|
| | | | | | Was pigging and flushing, was trying to pull a pipe apart when fell, left knee was caught in the brace of | |
| 23-011 | 5/3/2023 | 5/3/202 | 3 Distribution | WATER UTILITY WORKER I | a handicap ramp. Twisting knee. | left knee |
| 23-012 | 5/16/2023 | 5/16/202 | 3 Distribution | Please Select Job Title | pulling copper out of a residence when he felt a pop in his left shoulder. | left elbow |
| | | | | | Was in small gatehouse at Vadnais getting supplies to wash screen when stung by a bee. Right hand | |
| 23-013 | 5/19/2023 | 5/22/202 | 3 Production | SERVICE WORKER | and wrist are swollen/painful. Does plan to go to the doctor. | right hand and wrist |
| 23-014 | 5/18/2023 | 5/22/202 | 3 Production | WATER UTILITY WORKER I | helping scuba divers with gear, he was in the weeds, notice rash when changing. | both hands, forearms and nose |
| | | | | | Chipping gun in basement when either part of the gun broke off or a piece of concrete shot up and | |
| 23-016 | 5/30/2023 | 5/30/202 | 3 Distribution | WATER UTILITY WORKER I | went into chest | chest |
| | | | | | Employee was carrying the Bullet Machine down the basement stairs of a residence when he slipped | |
| 23-017 | 6/1/2023 | 6/1/202 | 3 Distribution | WATER SYSTEM WORKER II | on the stairs causing him to feel pain in his back. | Back |
| | | | | | Employee Was grinding out a sewer cover when a sliver of metal flew between his safety glasses and | |
| 23-018 | 6/22/2023 | 6/22/202 | 3 Distribution | WATER DISTRIBUTION SUPV II | into his eye. | Left Eye |
| | | | | | Employee was taking the cap off of a hydrant when the cap blew off hitting him in the stomach and | |
| 23-019 | 6/29/2023 | 6/29/202 | 3 Distribution | WATER DISTRIBUTION SUPV I | knocking him down. | Stomach |
| 23-020 | 6/28/2023 | 6/28/202 | 3 Distribution | WATER UTILITY WORKER II | pulling gate rod out of back of the work truck, felt pain in left shoulder and arm | left shoulder & arm |
| | | | | | | |
| 23-021 | 6/26/2023 | 7/11/202 | 3 Business | WATER METER TECHNICIAN | Aggravation of a prior work injury on 0107/2015 to lower back, was picking up a water meter. | lower back |
| | | | | | | |
| | | | | | | |