

APPLICATION FOR APPEAL

DEC 28 2011 CITY CLERK

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

The City Clerk needs the following to	process your appeal:	
\$25 filing fee payable to the City (if cash: receipt number	of Saint Paul) Letter which	YOUR HEARING Date and Time: Tuesday, / -/7 -/ Q Time/ 3 0 Location of Hearing: Room 330 City Hall/Courthouse
Address Being Appe	aled:	
Number & Street: 1849	Zeaner City:	St. Pau State: MN Zip: SS119
Appellant/Applicant: AMER	A22421 En	nail +MAZZAZI egmail.com
		Cell 612-799-7993
Signature		Date:
Name of Owner (if other than Appellan	nt):	
Address (if not Appellant's):		
Phone Numbers: Business	Residence	Cell
What Is Being Appea	led and Why?	Attachments Are Acceptable
Vacate Order/Condemnation/ Revocation of Fire C of O		
□ Summary/Vehicle Abatement		
≰ Fire C of O Deficiency List	Ceiling Hei	`s 5 A
ば Fire C of O: Only Egress Windows	Have width 1	let & if Botales 900
□ Code Enforcement Correction Notic	e	1 10100100
□ Vacant Building Registration		
Other .	#4 Bedreem	Size 7

* At time of inspection & Children 4/22/2011



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

December 15, 2011

TAMER AZZAZI 457 Snelling Ave N St Paul MN 55104-3802

FIRE INSPECTION CORRECTION NOTICE

RE:

1849 REANEY AVE

Ref. #110532

Residential Class: C

Dear Property Representative:

Your building was inspected on November 28, 2011 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A reinspection will be made on January 18, 2012 at 10:45 A.M.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. Basement SPLC 34.10 (4), 34.33 (3) Provide a bathroom floor impervious to water. Caulk the base run of the tub.
- 2. Basement UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work will require a permit(s). Call DSI at (651) 266-8989.-dryer duct is acordion type and is not a code product.
- Basement SPLC 34.13 (1) Provide and maintain all habitable areas with a ceiling height of 7 feet over 1/2 the floor area.-Ceiling height is 6feet and 2 inches

- 4. Basement bedroom west side SPLC 34.13 (3), SPLC 34.17 (2) Reduce and maintain the number of occupants in the sleeping rooms to: 1-Bedroom is 72 square feet. Bedroom is being occupied by 4.
- 5. Basement bedroom east side SPLC 34.13 (3), SPLC 34.17 (2) Reduce and maintain the number of occupants in the sleeping rooms to: 1-bedroom is 72 square feet.large enough for a one person occupancy.
- Bedrooms WEST SIDE and NORTH WEST SIDE MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-20inches openable height. Openable width is 26inches. Sill is 35inches. Glazed is 38inches in height by 24inches in width.
- 7. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 8. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office. Basement ceiling height is 6feet and 2inches in height.
- 9. SPLC 34.14 (2), 34.34 (5) Provide an approved Gas service adequate to meet the buildings needs. This work may require a permit(s), call DSI at (651) 266-9090.
- 10. SPLC 34.11 (6) Provide and maintain a minimum of 68 degrees F in all habitable rooms at all times.
- 11. MSFC 605.4 Discontinue use of all multi-plug adapters.
- 12. MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.
- 13. NEC 440.13 For cord-connected equipment such as room air conditioners, household refrigerators and freezers, drinking water coolers, and beverage dispensers, a separable connector or an attachment plug and receptable shall be permitted to serve as the disconnecting means. The appliance must plug directly into a permanent outlet.
- 14. SPLC 34.13 (2), (3), SPLC 34.17 (2) Reduce and maintain the number of occupants in the unit to: 7-House is occupied by 12 people.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: james.thomas@ci.stpaul.mn.us or call me at 651-266-8983 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

James Thomas Fire Inspector