

**Date:** February 08, 2018  
**File #:** 12 - 081569  
**Folder Name:** 554 CHARLES AVE  
**PIN:** 362923230073



**Date:** February 08, 2018  
**File #:** 12 - 081569  
**Folder Name:** 554 CHARLES AVE  
**PIN:** 362923230073



**Date:** February 08, 2018  
**File #:** 12 - 081569  
**Folder Name:** 554 CHARLES AVE  
**PIN:** 362923230073



**Date:** February 08, 2018  
**File #:** 12 - 081569  
**Folder Name:** 554 CHARLES AVE  
**PIN:** 362923230073



**Date:** February 08, 2018  
**File #:** 12 - 081569  
**Folder Name:** 554 CHARLES AVE  
**PIN:** 362923230073



**Date:** February 08, 2018  
**File #:** 12 - 081569  
**Folder Name:** 554 CHARLES AVE  
**PIN:** 362923230073



**Date:** February 08, 2018  
**File #:** 12 - 081569  
**Folder Name:** 554 CHARLES AVE  
**PIN:** 362923230073



Date: February 08, 2018  
File #: 12 - 081569  
Folder Name: 554 CHARLES AVE  
PIN: 362923230073





**Date:** February 08, 2018  
**File #:** 12 - 081569  
**Folder Name:** 554 CHARLES AVE  
**PIN:** 362923230073



**Date:** February 08, 2018  
**File #:** 12 - 081569  
**Folder Name:** 554 CHARLES AVE  
**PIN:** 362923230073





Date: February 08, 2018  
File #: 12 - 081569  
Folder Name: 554 CHARLES AVE  
PIN: 362923230073

# RECOMMENDED CHANGES IN GAS EQUIPMENT 014012

YOUR SERVICE MAN HAS DETERMINED THAT CHANGES IN YOUR GAS EQUIPMENT ARE  
RECOMMENDED AND A WARNING TAG HAS BEEN PLACED ON YOUR

CHANGE  WATER HEATER  FURNACE  OTHER \_\_\_\_\_

### THE PROBLEM TO BE CORRECTED IS

- |                                                        |                                                        |
|--------------------------------------------------------|--------------------------------------------------------|
| <input type="checkbox"/> DEFECTIVE GAS VALVE           | <input type="checkbox"/> GAS PIPING RESTRICTED         |
| <input type="checkbox"/> NOT INSTALLED PROPERLY        | <input type="checkbox"/> FAULTY ELECTRIC WIRING        |
| <input type="checkbox"/> IMPROPER VENTING              | <input type="checkbox"/> INADEQUATE CLEARANCE          |
| <input type="checkbox"/> IMPROPER GAS ADJUSTMENT       | <input type="checkbox"/> NON-COMBUSTIBLE               |
| <input type="checkbox"/> APPLIANCE NOT RETIRED TO CODE | <input type="checkbox"/> IMPROPER PIPING CONNECTIONS   |
| <input type="checkbox"/> IMPROPER SIZED GAS PIPING     | <input checked="" type="checkbox"/> OTHER (LIST BELOW) |

REASON FOR THE  GAS TIGHTNESS  CORRECTED BY \_\_\_\_\_  
 OTHER GAS WORK \_\_\_\_\_

NAME \_\_\_\_\_ PHONE # \_\_\_\_\_  
ADDRESS \_\_\_\_\_  
CITY \_\_\_\_\_

NAME \_\_\_\_\_ PHONE # \_\_\_\_\_  
ADDRESS \_\_\_\_\_  
CITY \_\_\_\_\_

REMARKS: THE NEW GAS TIGHTNESS REQUIREMENTS FOR GAS APPLIANCES  
AND PIPING ARE EFFECTIVE FROM THE DATE LISTED ON THIS TAG.

YOU HAVE BEEN ADVISED BY THE SERVICE MAN OF YOUR OBLIGATION THAT THESE  
CHANGES SHOULD BE MADE BY A QUALIFIED LICENSED PERSON IN  
ACCORDANCE WITH MANUFACTURER'S INSTRUCTIONS AND IN CONFORMITY  
WITH LOCAL, STATE AND REGULATIONS. ALTHOUGH THE EQUIPMENT MAY  
NOT FUNCTION AS BROUGHT HOME, CONTINUE USE WITHOUT THE  
RECOMMENDED IS NOT RECOMMENDED.

SIGNATURE OF SERVICE MAN \_\_\_\_\_ DATE \_\_\_\_\_

OK  NO  NO



THIS TAG IS THE PROPERTY OF THE SERVICE MAN AND SHOULD BE KEPT WITH THE EQUIPMENT.

**Date:** February 08, 2018  
**File #:** 12 - 081569  
**Folder Name:** 554 CHARLES AVE  
**PIN:** 362923230073



