Property Address:	1084 Euclid St	

 $Rating \ Key: \ M = Meets \ minimum \ B = Below \ minimum \ C = See \ Comment \ H = Hazardous \ Y = Yes \ N = No \ NV = Not \ Visible/Viewed \ NA = Not \ Applicable$

Item#

Comments

		Specify location(s), where necessary
BASEMENT/CELLAR		Areas concealed - finished off. Item ratings
1. Stairs and handrails	В	reflect only to what is readily visible.
2. Basement/cellar floor	M	,
3. Foundation	M	1. B Low headroom (less than 6' 8"). Improper
4. Evidence of dampness or staining	Y	rise / run. No guardrail on open side of
5. First floor, floor system	С	stairs. Improper handrail. Narrow stairs
6. Beams and columns	B,C	(less than 36").
		4. Stains at base of walls.
		5. C Missing joist hangers in areas.
ELECTRICAL SERVICE(S) # of Services	1	6. B Decay at post base(s). Improper notching
7. Service size:		of beams.
Amps: 30 60 100 _X 150 Other		6. C Splits noted in posts in areas.
Volts: 115 115/220 _X_		9. B Improperly routed NM wiring in areas.
BASEMENT ONLY:		Improperly supported NM type wiring in
8. Electrical service installation/grounding	М	areas.
9. Electrical wiring, outlets and fixtures		9. H Unrgrounded 3 prong outlets.
		10. C Cover secured - not fully evaluated.
		11. B ABS & PVC plastic glued together.
PLUMBING SYSTEM		13. H Uncapped dryer supply.
10. Floor drain(s) (basement)	<u>C</u>	14. B No cold water shut-off valve provided.
11. Waste and vent piping (all floors)	<u>B</u>	15. B Improper clearance to combustibles. Single
12. Water piping (all floors)	M	wall Class C flue piping requires 6"
13. Gas piping (all floors)	H	clearance to combustables. Missing screws
14. Water heater(s), installation	B	on flue.Three per joint required.
15. Water heater(s), venting	B	17C B Scale deposits noted under draft hood.
16. Plumbing fixtures (basement)	M	
HEATING SYSTEM(S) # of	1	
17. Heating plant(s): Type: <u>Water</u> Fuel: <u>Gas</u>		
a. Installation and visible condition	M	
b. Viewed in operation (required in heating season)		
c. Combustion venting	<u>B</u>	
The Evaluator is not required to operate the heating plan		
except during heating season, between October 15 and Ap	oril 15.	
18 Additional heating unit(a) Type: First		
18. Additional heating unit(s) Type: Fuel: _ a. Installation and visible condition		
b. Viewed in operation		
c. Combustion venting		
c. Combustion venting		
19. ADDITIONAL COMMENTS (1 through 18)		

1084 Euclid St Property Address: __

Rating Key: M = Meets minimum B = Below minimum C = See Comment H = Hazardous Y = Yes N = No NV = Not Visible/Viewed NA = Not Applicable
Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related.

Item # Comments

	KITCHEN		S
20.	Walls and ceiling	M	
21.	Floor condition and ceiling height	M	
	Evidence of dampness or staining	N	2
	Electrical outlets and fixtures	<u>B</u>	_
24.	Plumbing fixtures	M	3
	Water flow	<u>M</u>	
	···	<u>M</u>	5
27.	Condition of doors/windows/mech. exhaust	M	6
	LIVING AND DINING ROOM(S)		
	Walls and ceiling	<u>M</u>	
	Floor condition and ceiling height	<u>M</u>	
	Evidence of dampness or staining	N	
	Electrical outlets and fixtures	<u>M</u>	
	Window size and openable area	<u> </u>	
33.	Window and door condition	M	
٠.	HALLWAYS, STAIRS AND ENTRIES	Λ./	
	, 6,	<u> </u>	
	Evidence of dampness or staining	N	
	Stairs and handrails to upper floors	<u> </u>	
	Electrical outlets and fixtures	<u> </u>	
	Window and door condition	<u>M</u> Y	
39.	Smoke detector(s)	<u> </u>	
	Properly located* * Hard-wired (HWSD)	* V	
*if	N or H in a single family home then SPFire Dept requires	<u> </u>	lation
11	BATHROOM(S)	iivod iiistai	iation
40	Walls and ceiling	М	
	Floor condition and ceiling height	M	
41. 12	Evidence of dampness or staining	N	
42. 13	Electrical outlets and fixtures		
	Plumbing fixtures	M	
	Water flow	M	
	Window size/openable area/mechanical exhaust	M	
	Condition of windows/doors/mech. exhaust	M	
.,.	SLEEPING ROOM(S)		
48	Walls and ceiling	Μ	
	Floor condition, area, and ceiling height		
	Evidence of dampness or staining	N	
	Electrical outlets and fixtures	М	
	Window size and openable area	М	
	Window and door condition	М	
	ENCLOSED PORCHES AND OTHER RO	OOMS	
54.	Walls, ceiling, and floor, condition	M	
	Evidence of dampness or staining	N	
	Electrical outlets and fixtures	M	
	Window and door condition	M	
	ATTIC SPACE (Visible Areas)		
58.	Roof boards and rafters	C	
	Evidence of dampness or staining	NA_	
	Electrical wiring/outlets/fixtures	NA_	
	Ventilation	NA	
62.	ADDITIONAL COMMENTS (20 through 61)	C	
	CO Detector information reported here		

EVALUATOR:_____

Some floors out of level. Some upper sashes painted shut.

- 23. B Improperly supported receptacle in pantry
- 36. B Headroom less than 6'8". Improper rise /
- 58. C No visible attic access.
- 62. C State law requires CO detectors within 10' of bedroom doors.

Dan Brausen 10/24/2014 Page $\frac{3}{\text{Rev}} \frac{4}{3/2009}$ DATE: _

1084 Euclid St Property Address:

Rating Key: M = Meets minimum B = Below minimum C = See Comment H = Hazardous Y = Yes N = No NV = Not Visible/Viewed NA = Not Applicable

EXTERIOR (Visible Areas) Μ 63. Foundation C,B 64. Basement/cellar windows С 65. Drainage (grade) Μ 66. Exterior walls Μ 67. Doors (frames/storms/screens) В 68. Windows (frames/storms/screens) Μ 69. Open porches, stairways and decks Μ 70. Cornice and trim Μ 71. Roof structure and covering Μ 72. Gutters and downspouts В 73. Chimneys Μ 74. Outlets, fixtures and service entrance GARAGE(S)/ACCESSORY STRUCTURE(S) NA 75. Roof structure and covering NA 76. Wall structure and covering NA 77. Slab condition NA 78. Garage doors(s)..... NA 79. Garage opener(s) - (see important notice #6) . . _ NA 80. Electrical wiring, outlets and fixtures 81. ADDITIONAL COMMENTS (62 through 80) NA FIREPLACE/WOODSTOVES # of 0 NA 82. Dampers installed in fireplaces NA 83. Installation NA 84. Condition SUPPLEMENTAL INFORMATION No determination is made whether items meet minimum standards (Y/N, NA, NV, only)

Item# **Comments**

- 64. B Grade fill components in contact with window.
- 64. C Weathered areas.
- 65. C Landscaping restricts full viewing of
- 68. B Weathered/damaged in areas. Peeling paint.
- 73. B Loose/missing mortar. Loose brick.

INSULATION	Y/N	Type	Inches/Dept
85. Attic Insulation	NV		
86. Foundation Insulation	NV		
87. Kneewall Insulation	NV		
88. Rim Joist Insulation	NV		

89. ADDITIONAL COMMENTS (81 through 88) NA

I hereby certify I prepared this report in compliance with the St. Paul Evaluator Guidelines and all other applicable policies and procedures of the Truth-in-Sale of Housing Board. I have utilized reasonable and ordinary care and diligence and I have noted all conditions found that do not conform to the minimum standards of maintenance.

651-483-8407 10/24/2014 Page <u>4</u> of <u>4</u> **Evaluator Signature** Rev 3/2009 Phone Number Date

Dan Brausen **Printed Name:**

IMPORTANT NOTICES

- 1. Any single family residence in St. Paul must have at least one smoke detector connected to the electrical system (hard-wired). The detector must be located near sleeping rooms. For more information call Fire Prevention, 651-266-9090. (St. Paul Legislative Code, Chapter 58.)
- 2. Rainleaders connected to the sanitary sewer system must be disconnected. For more information call Public Works, Sewer Utility, (651) 266-6234.
- 3. A house built before 1978 may have lead paint on/in it. If children ingest lead paint, they can be poisoned. For more information call Ramsey County Public Health, 651-266-1199.
- 4. Neither the City of St. Paul nor the Evaluator is responsible for the determination of the presence of airborne particles such as asbestos, noxious gases such as radon, or other conditions of air quality that may be present, nor the conditions which may cause the above.
- 5. If this building is used for any purpose other than a single family dwelling, it may be illegally zoned. To help you determine legal uses under the zoning ordinance, contact the Zoning Administrator at 651-266-9008.
- 6. An automatic garage door should reverse upon striking an object. If it does not reverse it poses a serious hazard and should be immediately repaired or replaced.