

ADT



ADT




























Tenants damaged floor on the indicated circles. See photos from December 2017.















Original condition of attic entrance room.

