

Pat:

Attached are pictures of the house at the north end of my block on Jackson. Why didn't the city inspector cite this **place – look** at all the junk piled outside. The pictures taken on 12/5/18 show **doors, mattresses, and bed springs** piled outside. There is no garage door; the **fence** has been destroyed in more than 3 areas and the **gates broken and terminal fence poles bent**.

Some government agency put about \$30,000 or \$40,000 into this house after Adam and Elita moved in about 10 years ago **new roof, new siding, new insulation, new windows, new doors and door frames**, besides what was done to the inside **appliances, furnace**, etc. Now it's been **trashed and condemned** and the city is bitching about my **greenhouse**. Me, a 75-year old man recovering from 3 **major surgeries** and 6 months of **chemotherapy** in the last 4 years ... and still suffering from **neuropathy** and **muscle weakness**, having to put up with this harassment from the City of St. Paul.

Roger Stadler

Roger Stadler
12-10-18

RECEIVED

DEC 13 2018

Kelly & Lemmons, P.A.



Thrown out mattress &
and bed springs

Broken of rear door 1140 Jackson



Trash around the yard 1140 Jackson



Broken fence 1140 Jackson




Tank in yard 1140 Jackson



1140 Jackson

Note: About 10 years ago from 2018 this house had all new insulation, new roof, new siding, all new windows and doors, gutters installed by some government agency
Now the house is TRASHED.



Bent front fence 1140 Jackson



Broken front Gate at 1140 Jackson