PRECIMINARY BREAKDOWN

WORK PLAN - BREAKDOWN COST OF REHABILATION

(To be done in accordance with the Code Compliance Inspection Report) **Address:** 1565 7th ST E

WEEK OF	TASKS	CONTRACTOR	Supplies/Materials on hand (if any)	Needed Supplies/Materials	Owner/Developer Labor	Value of Cost
Jun 21.	Soffit Repair			Soffit Panels	OWNER	240.00
Jun 28	Basement WINDOW REPAIR		3 windows. /	3 ADD WINDOWS	OWNER	65x4 225.00
Jul 1.	MAIN LEVEL WINDOW			4 WINDOWS	OWNER	645
July 8	Roofing Repair	All Affordable. (cont)				5000.00
July 20	Plumbing	Rascher/McAllister Mech. (cont)		As per estimate.	Iside out	12685 TOTAL
	Roofing				inside out	7350 TOTAL
Aug 1st	Mechanical	McAllister MECH		DUCTWORK / FURNACE		12463.00 TOTAL
Sept. 1	ELECTRICAL			As per estimate.		4000 TOTAL

Total Project Cost: $ 28.860.

Note: (Code Enforcement Officers estimate the cost to repair this structure is $_____ to $_____).