PRECIMINARY BREAKDOWN

WORK PLAN - BREAKDOWN COST OF REHABILATION
(To be done in accordance with the Code Compliance Inspection Report) **Address:** 1565 747 ST E

WEEK OF	TASKS	CONTRACTOR	Supplies/Materials on hand (if any)	Needed Supplies/Materials	Owner/Developer Labor	Value of Cost
Jun 21.	Soffit Repair			Soffit Panels	OWNER	240.00
Jun 28	Basement WINDOW REPAIR		3 windows /	3 ADD WINDOWS	OWNER	65 x 4 225.00
Jul 1.	MAIN LEVEL WINDOW			4 WINDOWS	OWNER	645
July 8	Roofing Repair	ALL AFFORDABLE. (cont)				5000.00
July 20	Plumbing	Rascher/McALLISTER Mech. (cont)		AS PER estimate.	inside out	12685 TOTAL
	Roofing				inside out	7350 TOTAL
Aug 1ST	MECHANICAL	MCALLISTER MECH		DUCTWORK / FURNACE		12463.00 TOTAL
Sept. 1	ELECTRICAL			AS PER ESTIMATE.		4000 TOTAL

Total Project Cost: $ 28.860.

Note: (Code Enforcement Officers estimate the cost to repair this structure is $_____ to $_____).