CITY OF SAINT PAUL

375 Jackson Street, Suite 220 St Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-9124 Web: www.stpaul.gov/dsi

364.0

April 28, 2021

## NOTICE OF CONDEMNATION AS UNFIT FOR HUMAN HABITATION & ORDER TO VACATE

Nicholas Fasano 705 Magnolia Ave E St Paul MN 55106-3126

## Dear Sir or Madam:

The Department of Safety and Inspections, Division of Code Enforcement, has determined that the dwelling and premises at **705 MAGNOLIA AVE E** is "Unfit for Human Habitation". In accordance with Saint Paul Legislative Code, Chapter 34, Section 23, the premises will be placarded on **4-28-21** and ordered vacated no later than **4-28-21**.

Your attention is called to the following provisions of Section 34.23, Subsection 6 entitled, *Vacation of Structure or Unit*:

"Any dwelling unit, structure or portion thereof which has been condemned or placarded as unfit for occupancy shall be vacated within the time set forth in the placard and/or order. No person shall occupy or let for occupancy any structure which is condemned."

THIS DWELLING SHALL NOT AGAIN BE USED FOR HUMAN HABITATION UNTIL WRITTEN APPROVAL IS SECURED FROM THE CITY OF SAINT PAUL; DEPARTMENT OF SAFETY AND INSPECTIONS, DIVISION OF CODE ENFORCEMENT.

- <u>Principle Violations</u>: These deficiencies must be corrected before this condemnation and vacate order will be removed.
- 1.SPLC 34.23 **CONDEMNATION:** This occupancy is condemned as unsafe or dangerous. It constitutes a condition of material endangerment to occupants and emergency personnel. The interior of home has missing smoke and co detectors and the kitchen waste piping was removed. Inspector found feces and urine in the basement and possible sewer back up. There were very large holes in the foundation walls and possibly structurally unsound. The back porch post was not attached to the structure.
- 2.SPLC 34.15 **SMOKE DETECTOR:** The occupant of a dwelling unit must inform the owner of the dwelling unit of a nonfunctioning smoke detector within 24 hours of discovering that the smoke detector in the dwelling unit is not functioning. Smoke detector may not be tampered with or disabled at any time.
- 3.SPLC 34.15 **CARBON MONOXIDE ALARM:** Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturer's instructions.
- 4.SPLC 33.03 **PLUMBING:** Repair or replace and maintain all parts of the plumbing system to an operational condition. Permits may be required. KITCHEN SINK WAS REMOVED.
- 5.SPLC 34.09 **LOCKS/DEADBOLT:** Lacking deadbolt door locks. Provide one-inch throw deadbolt locks for all entry doors to dwelling unit(s). BOTH ENTRY DOORS MISSING LOCKS
- 6.SPLC 34.12 **SUPPLIED EQUIPMENT:** Repair and maintain all required and supplied equipment in an operative and safe condition to properly and safely perform their intended function in accordance with the provisions of the applicable code.
- 7.SPLC 45.03 **ELECTRIC COVER PLATES:** Provide electrical cover plates to all outlets, switches and junction boxes where missing. LIGHT FIXTURES NEED REPAIR.
- 8.SPLC 34.10 **WALLS:** All walls must be maintained in a sound condition and in a professional state of maintenance and repair.
- 9.SPLC 34.09 **FOUNDATION:** Provide and maintain foundation elements to adequately support this building at all points. Repair deteriorated or defective foundation in a professional state of maintenance and repair. The foundation shall be free of holes, breaks, loose or rotting boards or timbers and any other conditions which might admit dampness to the interior portions of the wall or to the interior spaces of structures. Permit may be required. LARGE HOLES IN BASEMENT FOUNDATION WALLS.

<u>Other Violations</u>: These deficiencies must be corrected in order to bring this property into compliance with the Saint Paul Legislative Code.

10.SPLC 34.10 **FLOORS:** All floors must be maintained in a sound condition and in a professional state of maintenance and repair. KITCHEN FLOOR.

11.SPLC 34.08 **EXTERIOR SANITATION:** All exterior property areas shall be maintained free from any accumulation of refuse, garbage or feces. Remove the accumulation of exterior storage that creates a nuisance or harbors rodents

Authorization to reoccupy this/these dwelling unit(s) will not be given until it is demonstrated that all principal violations have been corrected and that no new conditions exist which could constitute material endangerment or which threaten the peace, health, safety or welfare of the occupants of this building.

All repairs and new installations must be made in accordance with the appropriate codes. Permit information may be obtained from the Building Inspection and Design Section, 375 Jackson Street, Suite 220, (651) 266-8989.

You may file an appeal to this notice by contacting the City Clerk's Office at (651) 266-8585. Any appeal must be made in writing within 10 days of the date of this notice.

It is the responsibility of the property owner to keep all buildings secured and to properly maintain the premises at all times.

If you have any questions concerning this matter, please contact the Inspector, Paula Seeley, at 651-266-1916. To arrange an appointment or request an extension of time to complete repairs, you will need to speak directly to the inspector.

Sincerely,

## **Paula Seeley**

Enforcement Officer

ps

cc: Posted to ENS