RECEIVED

AUG 3 1 2010



## APPCICATION FOR APPEAL

Saint Paul City Clerk

310 City Hall, 15 W. Kellong Hall Saint Paul Minnesota 5031 2 Telephone: (651) 266-8369

	and the second s
The City Clerk needs the following to process your appeal:	Date and Time of Hearing
\$25 filing fee payable to the City of Saint Paul	Tuesday, Sept. 14
Copy of the City-issued orders or letter which are being appealed	Time 1:30
Attachments you may wish to include	Location of Hearing
This appeal form completed	Room 330 City Hall/Courtheyse
Appellant/Applicant: KEVIN ROSBACKA	
Address: 1743 MARLARET City: ST. PAUL State MN 219 55106	
Phone Numbers: Business Residence	Cellular <b>612-554-9839</b>
Signature: LA	Date 8/20/10
Name of Owner (if other than Appellant): EASTERN HTS, LUTH, CHURCH	
Address: 616 N. RUTH City: ST. PAUL State MN Zip 55119	
Phone Numbers: Business 451-735-4207 Residence	Celiular
State specifically what is being appealed and why (use an attachment if cocessory):	
PARSONAGE LOCATED AT	2127 MARGURET ST.
STIPAUL MN, APPENLING	ELARESS WINDOWS
IN AN EXISTING STRUCTURE.	
NOTE: Any person unsatisfied by the final decision of the City Council may obtain judicial review by timely filing an action as provided by law in District Court or Court of Appeals	Fee Received. Receipt Manage.
	Reviews (F. J. W. F.)

- Basement Storage Room SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling 3. in an approved manner.-Repair the holes in the storage room ceiling.
- Egress Windows Main Floor and Basement Bedrooms MSFC1026.1 Provide and 4. maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651) - 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information. W-869de

GLERKY

(1)

## Main Floor Southeast, Northwest and Southwest Bedroom (Double-hung)

19.5 h x 25 w - Openable

41 h x 24 w - Glazed

## Basement Bedroom (Double-hung)

20.5 h x 25 w - Openable

41 h x 24 w - Glazed

- Exterior Driveway SPLC 163.03, 163.01 (2), (3) Currently license (tabs) all vehicles 5. on the property and return the vehicles to an operative mechanical condition or remove vehicles from the property.-Inoperable vehicle with collector plate 709-654.
- 6. Garage - Ceiling - MSFC 703 - Provide and maintain fire rated floor and/or ceiling construction with approved materials and methods. This work may require a permit(s). Call DSI at (651) 266-9090.-Secure the missing attic access panel so fire separation can be maintained between the garage and residence.
- Main Floor Bathroom MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-9090.-Repair/replace the inoperable vent fan.
- Main Floor Bathroom SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in
- Main Floor South Entry Door SPLC 34.09 (3), 34.32 (3) Repair and maintain the door in good condition.-Provide a seal around the south entry door.
- Main Floor Southeast Bedroom SPLC 34.09 (3), 34.32 (3) Repair and maintain the window in good condition. The window is not staying in the open position.
- Main Floor Southeast and Northwest Bedroom SPLC 34.09 (3), 34.32 (3) Repair and 11. maintain the window glass.-Replace the broken window pane in main floor southeast and
- Main Floor and Basement Bedrooms SPLC 34.09 (3), 34.32 (3) Repair and maintain 12. the window lock.-Repair/replace the inoperable window locks in the main floor northwest and southwest bedroom and basement bedroom.