

□ Other

APPLICATION FOR APPEAL

RECEIVED

SEP 2 4 2010

CITY CLERK

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

The City Clerk needs the following to		YOUR HEARING Date and Time:
\$25 filing fee payable to the City (if cash: receipt number 33742		Tuesday, October S
Copy of the City-issued orders o		
are being appealed		Time_ 1:30 y.M.
□ Attachments you may wish to in	clude	Location of Hearing:
☐ This appeal form completed		Room 330 City Hall/Courthouse
Address Being Appe	ealed:	
Number & Street: 1783 I	DAYPON ALECity: 3	PAUL State MH Zip: 55/07
MARIC	CANU	nail MRF/X/TMN @GMAIL: CO
Appellant/Applicant: /////	Err	nail MKF/X///M/Y (BC) MITIC: CO
Phone Numbers: Business	Residence	Cel 00/770-578
		Date: 9/24/10
Signature:		Date: // 1-9/10
Name of Owner (if other than Appella	nt): 6 ARY JAG	ER.
Address (if not Appellant's): 393	HIGHPOINT (CIRVE MAPIELVAD 551
Phone Numbers: Business	Residence	3)-8611 cel 05//402-430/
YA71 (Y Y)		
What Is Being appea	led and why?	Attachments Are Acceptable
Vacate Order/Condemnation/		
Revocation of Fire C of O	B POVIDE PRE	PERLY SIZED DOOR
□ Summary/Vehicle Abatement	FOR ENTRY	PUHIT.
□ Fire C of O Deficiency List	to 0	
☐ Fire C of O: Only Egress Windows	- POVIDE A	APPROVED CEILING
Code Enforcement Correction Noti	ice) HELBAT DT	= B4", CLRENT
□ Vacant Building Registration	CEILING. 15	78.5" HIGHEST
□ Other	CFILING WE	SAN PROVIDE IS
□ Other	721211	16.1205 DADE CLE

Fire Inspection Division

Robert Kessler, Director

CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, MN 55101-1806

Telephone: 651-266-8989 Fax: 651-266-8951



September 15, 2010

GARY JAGER ANDREA JAGER 383 HIGHPOINT CURVE MAPLEWOOD MN 55119-6759

CORRECTION NOTICE - RE-INSPECTION COMPLAINT

RE: 1783 DAYTON AVE

Dear Property Representative:

A re-inspection was made on your building on September 14, 2010, in response to a complaint. You are hereby notified that the following deficiencies must be corrected prior to re-inspection date.

A re-inspection will be made on October 12, 2010 at 10:00 AM.

Failure to comply may result in a criminal citation or the revocation of the Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Certificate of Occupancy. The code also provides for the assessment of additional re-inspection fees.

DEFICIENCY LIST

- 1st Floor SPLC 34.09 (3), 34.32 (3) Repair and maintain the door in good condition.-Repair kitchen 1. door to allow it to open fully.
- 1st Floor SPLC 34.09 (3) i Provide and maintain an approved one-inch throw single cylinder deadbolt 2. lock.-For kitchen door.
- Basement Unit SPLC 34.10 (7), 34.33 (6) Repair and maintain the walls in an approved manner. 3. -Repair or replace the damaged or deteriorated wall coverings and paint the wall.
- Basement Unit SPLC 34.12 (2), 34.35 (1) Repair and maintain all required and supplied equipment 4. in an operative and safe condition. -Repair or replace missing stove from basement unit.
- Basement SPLC 34.10 (3), 34.33(2) Provide an approved handrail. The top of the handrail must be 5. between 34 and 38 inches above the treads and run the entire length of the stair.
- Basement SPLC 34.10 (3), 34.33(2) Repair or replace the unsafe stairway in an approved manner. 6.

- 7. Basement MSFC 703 Repair and maintain the required fire resistive construction with approved materials and methods. This work will require a permit(s). Call DSI at (651) 266-9090. -Contact a licensed contractor to provide an approved fire separation under permit, between both dwelling units and through the exit path for the basement unit.
- 8. Basement Unit SPLC 34.09 (3), 34.32 (3) Repair and maintain the door in good condition.
 -Provide an approved rated and properly sized door for entry to unit. The unrated door height measured 74.5 inches.
- 9. Basement Unit SPLC 34.13 (1) At least half of the floor area of any habitable room shall have a clear ceiling height of seven feet (84 inches) or more.
 -Provide an approved ceiling for the basement unit. The basement unit has 192 square feet with a ceiling height of 78.5 inches and 16.4 square feet with a ceiling height of 73 inches.
- 10. Exterior West SPLC 34.09 (3), 34.32 (3) Repair and maintain the window glass.-Repair broken window pane.
- Exterior SPLC 34.09 (1) e, 34.32 (1) d Provide and maintained the roof weather tight and free from defects.-Paint the fascia.
- Exterior NFPA 211,9-2 Have the chimneys, fireplaces, and vents inspected for soundness, freedom from deposits, and correct clearances. Cleaning, maintenance, and repairs shall be done if indicated by the inspection.
 Contact a licensed contractor to repair damaged chimney. This work may require a permit. Contact
 - DSI at 651-266-8989.
- 13. Exterior SPLC 71.01 The address posted is not visible from street. (HN-1)-Both front and on garage. Provide reflective numbers or background or illuminate at night.
- Interior Throughout MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-9090.
 Contact a licensed electrician to provide a ground for non-grounded 3 prong outlets or provide an approved outlet.
- 15. Interior SPLC 34.10 (1) Abate and maintain the basement reasonably free from dampness and free of mold and mildew.
- Interior MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-9090.
 -Contact a licensed electrician to provide a ground for non-grounded GFI outlets or label them as -NO EQUIPMENT GROUND-.
- 17. Interior MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.-Throughout.
- 18. Porch SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner.-Repair or replace the damaged or deteriorated ceiling.

For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

If you have any questions, email me at william.beumer@ci.stpaul.mn.us or call me at 651-266-8991 between 7:30 a.m. - 9:00 a.m.

Please help to make Saint Paul a safer city in which to live and work.

Sincerely,

William Beumer Fire Inspector

Ref. # 101609